

TOWNSHIP 21 RANGE 09 POINT IDENTIFIER # 400400

PRIMARY CORNER DESCRIPTION Cor. Secs. 15, 16, 21, & 22

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 945-6)

Set Alder post, 4½" long, 4" sq., 24" in the ground on steep hillside sloping S for cor. of secs. 15, 16, 21, & 22, marked T21S S15 on NE, R9W S22 on SE, S21 SW, & S16 on NW faces with 3 notches on the S and E edges; from which

A Fir, 24" dia., bears N.15°30'E., 57 lks., mkd: T21S R9W S15 BT.

A Fir, 24" dia., bears S.47°30'E., 65 lks., mkd: T21S R9W S22 BT.

A Fir, 30" dia., bears S.53°15'W., 130 lks., mkd: T21S R9W S21 BT.

A Fir, 30" dia. bears N.32°W. 17 lks. mkd: T21S R9W S16 BT

BLM dependent resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #350 & 511, surveyed April 1966/May 1967 - (DCSO records, Vol. 34 Page(s) 14242-3)

The cor. of secs. 15, 16, 21, & 22, determined at the record bearing & dist. from the orig. BTs:

The stump hole of a fallen & decayed fir, 35" dia., bears N.15½°E., 57 lks.

A Fir, 38" dia., bears N.32°W., 17 lks. with healed blaze.

At the corner point

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T21S	R9W
<u>S 16</u>	<u>S 15</u>
S 21	S 22
1966	

from which new BTs:

A cedar, 30" dia., bears N.73°E., 42 lks., mkd: T21S R9W S15 BT.

A Fir, 10" dia., bears S.18½°E., 56 lks., mkd: T21S R9W S22 BT.

A Hemlock, 22" dia., bears S.57°W., 109 lks., mkd: T21S R9W S21 BT.

Fd. Ok by Les Roberts, March 1983 - M 94-4

Ron Quimby - Crew: N. Fromdahl - 1/2020 - C.S. File 65/104-33

Found - BLM brass cap (properly mkd)

27" Fir N.74°W., 7.4 ft. good scar no record.

26" Fir N.2°W., 53.5 ft. good scar no record.

These trees were done after M94-4 was done.

New - 10" Fir S.26°E., 16.3 ft. scribed T21S R9W S22 BT.

9" Fir N.86°E., 27.5 ft. scribed T21S R9W S15 BT.

Compass decl. 15½°E.