

PRIMARY CORNER DESCRIPTION Cor. Secs. 3 & 10 only (west side)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 950)

Set Alder post, 4½ ft. long, 4" sq., 24" in the ground on steep hill side, sloping North for cor. of secs. 3, 4, 9, & 10, mkd: T21S S3 on the NE., R9W S10 on the SE, S9 on the SW., and S4 on the NW faces with 5 notches on the S and 3 notches on the E edges, from which

- A Fir, 36" dia., bears N.12°30'E., 290 lks., mkd: T21S R9W S3 BT.
- A Fir, 80" dia., bears S.82°30'E., 260 lks., mkd: T21S R9W S10 BT.
- An Alder, 6" dia., bears S.70°W., 77 lks., mkd: T21S R9W S9 BT.
- A Fir, 30" dia., bears N.13°30'W., 225 lks., mkd: T21S R9W S4 BT.

BLM dependent resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #350 & 511, surveyed April 1966/May 1967 - (DCSO records, Vol. 34 Page(s) 14245)

Point for the cor. of secs. 3 & 10 only, at proportionate dist. in latitude, and at rec. dist. in departure, from the ¼ sec. cor. of secs. 3 & 10; there is no remaining evidence of the orig. corner.

Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked: T 21 S R 9 W
 S 9 |S 3
 |S 10
 1966

- from which
- A Fir, 31" dia., bears N.49½°E., 54 lks., mkd: T21S R9W S3 BT.
 - A Hemlock, 12" dia., bears S.45°E., 9 lks., mkd: T21S R9W S10 BT.

Fd. OK 12/1990 - M 111-27