

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 932)

A Fir, 10" dia., which I marked ¼ S on W face for ¼ sec. cor., from which

A Fir, 6" dia., bears N.53°E., 17 lks., mkd: ¼ S BT.

A Fir, 10" dia., bears S.45°W., 10 lks., mkd: ¼ S BT.

BLM dependent resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #350 & 511, surveyed April 1966/May 1967 - (DCSO records, Vol. 34 Page(s) 14232-3)

From the ¼ sec. cor. of secs. 22 & 23, occupied by the orig. corner tree, a fir, 20" dia., with scribe marks ¼ S visible on opened blaze, on W side, from which the orig. BTs:

A decayed fir stump, 10" dia., bears N.53°E., 17 lks., with no marks remaining.

A decayed fir stump, 18" dia., bears S.45°W., 10 lks., with no marks remaining.

and a monument for which I have no record:

An iron pipe, 2" dia., extending 24" above ground firmly set, bears S., 3 lks., with steel cap marked ¼ S 22 23.

and new BTs

A Fir, 4" dia., bears S.67°E., 30 lks., mkd: ¼ S23 BT.

A Fir, 5" dia., bears S.75°W., 35 lks., mkd: ¼ S22 BT.

BLM dependent resurvey by John A. Farmer, Cadastral Surveyor, under Group #1399, surveyed Aug./Sept. 1987 - (DCSO records Vol. 48 Page(s) 18453)

The 1/4 sec. cor. of secs. 22 & 23, monumented with the original corner tree, a fir, 26" diam., with healed blaze on the W. side, from which the remains of an orig. bearing tree:

A decayed Fir stump, size indeterminate, bears S.45°W., 10 lks. with scribe marks ¼ S BT visible on open face.

and bearing trees by Peterson

A fir, 14" dia., bears S.67°E., 30 lks. with healed blaze.

A fir, 9" dia. bears S.75°W., 35 lks., with healed blaze.

and local corner reported by Peterson

An iron pipe, 2" diam., firmly set, projecting 18" above ground with steel cap mkd ¼ S22 S23, bears South, 3 lks and a new reference monument

A stainless steel post, 28" long, 2½" diam., set 24" in the ground, for a reference monument, bears N.40½°E., 15 lks., with brass cap mkd. RM ¼ S23 1987, and an arrow pointing to the corner.

continued next page

TOWNSHIP 21 RANGE 09 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.
The corner is located 300 lks. N of an old logging road, bears E & W

Dependent resurvey by Boyd W. Peterson, Cadastral Surveyor, under Group #1735, surveyed June 1994/March 1995. (DCSO rec Vol. 52 Pgs 19695)

The 1/4 sec. cor. of secs. 22 & 23, monumented with the original corner tree, a fir, 28" diam., with healed blaze on the W. side, from which bearing trees by Peterson:

A fir, 9" dia., bears S.67°E., 30 lks., with healed blaze.

A fir, 17" dia. bears S.75°W., 35 lks., with healed blaze.
and local corner reported by Peterson

An iron pipe, 2" diam., firmly set, projecting 18" above ground with steel cap mkd ¼ S22 S23, bears South, 3 lks and a reference monument by Farmer

A stainless steel post, 2½" diam., firmly set, projecting 6" above ground, bears N.40½°E., 15 lks., with brass cap mkd. RM ¼ S23 1987, and an arrow pointing to the true corner point.