

PRIMARY CORNER DESCRIPTION Cor. Secs. 14, 15, 22, & 23

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 933)

-----  
Set sandstone 16x12x4" 12" in the ground on hillside sloping SE for Cor. to secs. 14, 15, 22, & 23 marked with 3 notches on the S & 2 notches on the E sides, from which

- A Cedar, 8" dia., bears N.3°30'E., 72 lks., mkd: T21S R9W S14 BT.
- A Fir, 16" dia., bears S.31°30'E., 25 lks., mkd: T21S R9W S23 BT.
- A Cedar, 46" dia., bears S.42°30'W., 60 lks., mkd: T21S R9W S22 BT.
- A Fir, 8" dia., bears N.22°W., 118 lks., mkd: T21S R9W S15 BT.

BLM dependent resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #350 & 511, surveyed April 1966/May 1967 - (DCSO records, Vol. 34 Page(s) 14233)

-----  
Point for the cor. of secs. 14, 15, 22, & 23 proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28 long, 2½" dia., 25" in the ground, with brass cap marked:

T21S R9W  
S 15 | S 14  
S 22 | S 23  
1966

from which

- A Fir, 10" dia. bears N.67°E. 61 lks. mkd: T21S R9W S14 BT
- A Fir, 12" dia. bears S.6°E., 46 lks. mkd: T21S R9W S23 BT
- A Fir, 8" dia. bears S.47°W. 37 lks. mkd: T21S R9W S22 BT
- A Fir, 5" dia. bears N.38°W., 40 lks. mkd: T21S R9W S15 BT

Tony Hostetter - For: Roseburg Resources - January 2000 - C. S. File 65/30-4 thru 7

-----  
Found - 1966 BLM brass cap  
20" Fir, face evident, BLM tag, bears N.68°E., 40.5 ft. to center.  
BT @ S.6°E., is uprooted  
18" Fir, face evident, BLM tag, bears S.46°W., 24.7 ft. to center.  
16" Fir, face evident, BLM tag, bears N.36°W., 26.3 ft. to center.  
New BT - 22" Cedar, faced & scribed "S23 NW BT", BT tag, bears S.20°E., 16.5 ft. to 6" spike placed in root collar.