

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 35 only, T20-9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 321)

-----  
Set a post (Maple), 5 ft. long, 4" sq., 24" in the ground, marked ¼ S on N. face, for ¼ sec. cor, from which

An Alder 8" dia., S.69½°W., 40 lks. dist., mkd. ¼ S BT.

A Maple 4" dia., bears N.17½°E., 5 lks. dist. mkd. ¼ S BT.  
The post stands between 4 windfalls.

Fd. and used in GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608 -dated April 17, 1893 - (DCSO records Vol. 1 Page(s) 368)

BLM Resurvey by Thomas A. Tillman and Joseph S. Gawron, Cadastral Engineers, under Group #306, surveyed May 1953/Oct. 1954 - (DCSO records Vol. 29 Page(s) 12453)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap mkd:

¼ S 35  
1954

from which

A Maple 20" dia., bears N.20½°E., 29 lks. dist. mkd. ¼ S35 BT.

A Hemlock 8" dia., bears N.61°W., 36 lks. dist. mkd. ¼ S35 BT.

BLM resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #'s 350 & 511, surveyed Apr. 1966/May 1967 (DCSO records Vol. 34 Page(s) 14221)

-----  
The ¼ sec. cor., monumented with an iron post 1" dia., extending 4" above ground, firmly set, with brass cap mkd. in 1954,

from which bearing trees mkd. by Tillman in 1954:

The stump hole of a fallen and burned Maple 20" dia., bears N.20½°E., 29 lks. dist., with healed blaze.

The stump hole of a fallen and burned Hemlock 11" dia., bears N.61°W., 36 lks. dist., with fragmentary scribe marks visible on burned blaze.

and new bearing trees:

A burned Fir snag 67" dia., bears N.62°E., 120 lks. dist. mkd. ¼ S35 BT.

A burned Maple snag 20" dia., bears N.58½°W., 39 lks. dist. mkd. ¼ S35 BT.

(Cont. Next Page)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Les Roberts - For: International Paper Co. - March 1984 - M 96-26 and C.S. File 58/280

-----  
Found - 1954 GLO brass cap, properly mkd., set firmly in ground.  
1954 BTs gone.  
17" Maple stump N.58°W., 26.6 ft. (no marks) (1966 rec. N.58¼°W., 25.7 ft.)  
63" Fir stump bears N.62°E., 78.5 ft., scribe visible. (1966 BT rec. N.62°E., 79.2 ft.)  
42" Cedar snag S.35°W., 25.6 ft., no marks, International paper location tag nail to snag. (No rec.)

Set metal fence post beside brass cap. Wired survey attention sign to fence post.

Cor. lies on top of narrow ridge. Ridge runs N.45°E. and S.45°W. Cor. is in stand of 15-20 year old reproduction.

-----  
Douglas Co. Surveyors Office - L.E. Monrean, Deputy - R. Smith; S. Flause, crew - April 4, 1984 - C.S. File 62/18-5

-----  
Found - 1954 GLO brass cap, properly mkd. on a 1" I.P. protruding 4" above ground.  
No original evidence found.  
No evidence of 1954 resurvey found.  
A 1967 BLM BT, 67", now a 63", 3 ft. high Fir stump with scribing visible "¼ S35 BT", bears N.65°E., 78.5 ft. (Rec. N.62°E., 79.2 ft.)  
A 1967 BLM BT, 20" now a 17", 4 ft. high Maple stump, bears N.58°W., 26.6 ft. per M 96-26 (Rec. N.58¼°W., 25.7 ft.)  
New BTs- 6" D.Fir double blazed and scribed "¼ S35 CS BT", bears N.71½°E., 7.1 ft.  
4" D.Fir double blazed and scribed "X BT", bears N.21°W., 5.9 ft.

Sketch in file.

-----  
Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2286, surveyed Oct. 2009 - (DCSO records Vol. 56 Page(s) 22329)

-----  
The ¼ sec. cor. of sec. 35 only, on the S. bdy. of T. 20 R9W reestablished by proportionate measurement by Tillman & Gawron in 1953-54, rehabilitated by Peterson in 1966-67, utilized by Roberts, in 1984, & rehabilitated by Monrean, in 1984, & by Forkner in 2006-09; monumented with an iron post, 1" dia., firmly set, projecting 3" above ground, with a brass cap (properly) mkd. continued next page

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 35 only, T20-9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

from which the remains of the bearing trees mkd. by Peterson  
A decayed fir stump, 75" dia., bears N.62°E., 79.2 ft., no marks visible.  
A decayed maple stump with sprouts, the largest of which is 7" dia., bears N.58½°W., 25.7 ft., no marks visible.  
and the remains of the BTs mkd. by person(s) unknown and reported by Roberts  
A burned cedar snag, 40" dia., bears S.35°W., 25.6 ft., no marks visible.  
and the remains of the BTs mkd. by Monrean  
A fir, 9" dia., bears N.71½°E. 7.1 ft. with a healed blaze  
A fir snag, 6" dia bears N.21°W. 5.9 ft with healed blaze  
and a bearing tree by Forkner  
A hemlock, 15" dia., bears N.80°W., 42.8 ft., with scribe marks ¼ S35 BT visible on partially healed blaze and a Mag Nail on the right side center.  
A steel fence post with USFS tag is alongside the cor.  
Corner is located, E., 70 ft., of the top of a knob, on the N. side; W., 205 ft., of a dirt road, 8 ft. wide, extending S.70°W. and E. for 95 ft. before turning S.50°E.; and W., 370 ft., of another dirt road, 8 ft. wide, extending N.15°W. and S., with a tank trap to N. and S.

BLM corrective remonumentation and rehabilitation of certain corners by Edith M Forkner, Cadastral Surveyor, under Group #2000, surveyed Feb. 2006/March 2009 - (DCSO records Vol. 58 Page(s) 23077-8)

-----  
The ¼ sec cor. of sec. 35 only, monumented with an iron post, 1" dia., firmly set, projecting 4" above ground, with brass cap (properly) mkd.  
from which the remains of the bearing trees mkd. by Peterson in 1966-67  
A decayed fir stump, 74" dia., bears N.62°E., 79.2 ft., with illegible scribe marks visible on badly decayed blaze.  
A clump of maple trees bears N.58½°W., 25.7 ft., no marks visible.  
and the remains of a bearing tree mkd. by person(s) unknown, recovered by Roberts, in 1984  
A burned cedar snag, 42" dia., bears S.35°W., 25.6 ft., no marks visible.  
and the remains of the bearing trees mkd. by Monrean, in 1984  
A fir, 8" dia., bears N.71½°E., 7.1 ft. with a healed blaze.  
A fir snag, 6" dia., bears N.21°W., 5.9 ft. with a healed blaze.

continued next page

TOWNSHIP 21 RANGE 09 POINT IDENTIFIER # 528700

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 35 only, T20-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and a new bearing tree

A hemlock, 14" dia., bears N. 80° W., 42.8 ft. mkd. ¼ S35  
BT.

A steel fence post with property sign is alongside the cor.