

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 11 & 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 936)

Set Fir post, 5 ft. long, 4" sq., 24" in the ground on steep hillside sloping E for ¼ sec. cor., mkd: ¼ S on N face; from which

A Fir, 15" dia., bears S.83°E., 29 lks., mkd: ¼ S BT.

A Fir, 16" dia., bears N.8°W., 27 lks., mkd: ¼ S BT.

BLM dependent resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #350 & 511, surveyed April 1966/May 1967 - (DCSO records, Vol. 34 Page(s) 14236)

Point for ¼ sec. cor. of secs. 11 & 14, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked:

¼ S 11

S 14

T21S R9W

1966

from which

A Fir, 8" dia., bears N.59°W., 16 lks., mkd: ¼ S11 BT.

A Fir, 6" dia., bears S.42°E., 23 lks., mkd: ¼ S14 BT.

Clyde Mulkins - For: I.P. Timber Operating Co. LTD - March 1996 - M 123-67

Found - 1966 BLM brass cap at the corner.

14" D.Fir with a healed face, bears N.59°W., 16 lks.

11" D.Fir with a healed face, bears S.42°E., 23 lks.

New BTs- 13" D.Fir bears N.13°E., 15.0', scribed "¼ S11 BT"

14" D.Fir bears S.46°W., 23.5', scribed "¼ S14 BT"

The Corner falls on a ridge top - Also falls 60 east of gravel road.