

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 11

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 938)

-----  
Set fir post, 4½ ft. long, 4" sq., 24" in the ground on steep hillside sloping North for ¼ sec. cor., mkd: ¼ S on N face; from which

- A Fir, 6" dia., bears N.2°E., 20 lks., mkd: ¼ S BT.
- A Fir, 12" dia., bears S.80°E., 19 lks., mkd: ¼ S BT.

BLM dependent resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #350 & 511, surveyed April 1966/May 1967 - (DCSO records, Vol. 34 Page(s) 14238)

-----  
Point for ¼ sec. cor. of secs. 2 & 11, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28" long, 2½" dia., 25" in the ground, with brass cap marked:

¼ S 2  
S 11  
T21S R9W  
1967

- from which
- A Hemlock, 5" dia., bears N.70°W., 87 lks., mkd: ¼ S2 BT.
  - A Fir, 6" dia., bears S.61°E., 7 lks., mkd: ¼ S11 BT.

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2286, surveyed Oct. 2009 - (DCSO records Vol. 56 Page(s) 22342)

-----  
The ¼ sec. cor. of secs. 2 & 11, reestablished by proportionate measurement by Peterson in 1966-67; monumented with an iron post, 2½" dia., firmly set, projecting 2" above ground, with a brass cap (properly) mkd.

from which the bearing tree mkd. by Peterson

- A fir, 28" dia., bears S.61°E., 4.6 ft., with a healed blaze.

and a new bearing tree

- A fir, 25" dia., bears N.23°W., 11.9 ft., mkd. ¼ S2 BT.

Corner is located at the base of a boulder, 3 ft. high, 6 ft. wide.