

PRIMARY CORNER DESCRIPTION Cor. Secs. 1, 2, 11, & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 924-5)

Set fir post, 4½ ft. long, 4" sq., 24" in the ground on hill side sloping SW for cor. of secs. 1, 2, 11, & 12, marked T21S S1 on NE, R9W S12 on SE, S11 SW, S2 on the NW faces with 5 notches on the S and 1 notch on the N edges, from which

- A Fir, 8" dia. bears N.28°E., 14 lks. mkd: T21S R9W S1 BT.
- A Fir, 10" dia. bears S.2°E., 9 lks. mkd: T21S R9W S12 BT.
- A Fir, 18" dia., bears S.87°W., 33 lks., mkd: T21S R9W S11 BT.
- A Hemlock, 10" dia., bears N.77°W., 18 lks., mkd: T21S R9W S2 BT.

BLM dependent resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #350 & 511, surveyed April 1966/May 1967 - (DCSO records, Vol. 34 Page(s) 14229-30)

The cor. of secs. 1, 2, 11, & 12, determined at the record bearing & dist. from the remains of the orig. BTs:

- A Fir root crown, 14" dia., bears N.28°E., 14 lks., with no marks remaining.
- A rotted & burned Fir stump, 18" dia., bears S.87°W., 33 lks. with scribe marks T21S R9W S11 BT visible on opened blaze.

At the corner point

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T21S R9W	
S 2	S 1
S 11	S 12
1966	

from which

- A Fir, 6" dia. bears N.3°E., 89 lks., mkd: T21S R9W S1 BT.
- A Fir, 6" dia. bears S.8°E. 101 lks. mkd: T21S R9W S12 BT.
- A Fir, 11" dia. bears S.34°W. 83 lks. mkd: T21S R9W S11 BT
- A Fir, 10" dia. bears N.53°W. 42 lks. mkd: T21S R9W S2 BT.

Mark Smalley - For: Roseburg Forest Products - Mar. 13, 1997
- C.S. 65/13-9C

Found - 1966 BLM IPBC
20" Fir, N.3°E., 89 lks. - good healed face.
26" Fir, S.34°W., 83 lks.- good healed face.

New Accessories -

- 6" Fir, N.27°W., 18' scribed "S2 BT".
- 7" Fir, S.10°E., 20.2' scribed "S 12 BT".

cont.

TOWNSHIP 21 RANGE 09 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Cor. Secs. 1, 2, 11, & 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2286, surveyed Oct. 2009 - (DCSO records Vol. 56 Page(s) 22337)

The cor. of secs. 1, 2, 11, and 12, remonumented by Peterson in 1966-67, and rehabilitated by Smalley, in 1997; monumented with an iron post, 2½" dia., firmly set, with top 22" below the surface of the ground, with a brass cap (properly) mkd. from which the bearing trees mkd. by Peterson

A fir, 24" dia., bears N.3°E., 58.7 ft., with a healed blaze.

A fir, 37" dia., bears S.34°W., 54.8 ft., with a healed blaze.

and the bearing trees mkd. by Smalley

A fir, 10" dia., bears S.9°E., 20.3 ft., with a healed blaze.

A fir, 7" dia., bears N.26½°W., 17.9 ft., with a healed blaze.

An aluminum fence post with International Paper Company sign is alongside the cor.

Corner is located in the fill bank of an overgrown graveled road, 6 ft. wide, extending N.65°E. and S.80°W., and E., 735 ft., of Scare Creek, 15 ft. wide, course N.5°W., near W. edge of bottom land, 200 ft. wide.