TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 100239

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 25 only, T21-11

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page(s) 1191)

Set a sandstone 8x8x8 ins., 5" in the ground for ¼ sec. cor. mkd. ¼ S on W. face, and raised a mound of stone 1½ ft. high, 3 ft. base, alongside, pits impracticable.

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1053)

Apportioned distance.
Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for ¼ sec. cor. of sec. 25 only, with brass cap mkd:

¼
S25|
1919

from which
A Fir 6" dia., bears S.40°W., 32 lks. dist. mkd. ¼ S25 BT
A Fir 14" dia., bears N.37°W., 26 lks. dist. mkd. ¼ S25 BT

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - July 18, 1968 - C.S. File 54/1-5

Found - Concrete filled I.P. in place, but no trace of GLO brass cap.
Orig. 6" now 22" Fir, alive, S.40°W., 21.1 ft., shows good scar. We do not open. Rescribe "¼ S25 CS BT"
Orig. 14" now 22" Fir, down, N.37°W., 17.2 ft., shows good scar.

Set Brass cap at cor. mkd: County Surveyors Office
T 21 S R 11 W
¼ S25|R10W
1968

New BT - 24" D.Fir N.52°W., 43.8 ft. mkd. ¼ S25 CS BT.
This corner lies 47.2 ft. South of the W¼ sec. 30 on very steep NE slope, approx. 43 ft. S. of top of spur sloping NE.