TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 100440

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. Sec. 18 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1057)

Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for ¼ sec. cor. of sec. 18 only, with brass cap mkd: ¼
S 18
1919

from which
A Hemlock 14" dia., bears N.62°E., 30 lks. dist. mkd. ¼ S18 BT.
A Cedar 24" dia., bears S.23°E., 8 lks. dist. mkd. ¼ S18 BT.

Survey by Herman Pieske, RLS 1651 - For: U.S. Forest Service Nov. 1984 - M 97-77 A&B

Found - 1½" I.P. with brass cap broken off. (1919 GLO)
32" Cedar bears S.23°E., 5.3 ft. healed face.
24" Hemlock bears N.62°E., 19.8 ft. healed face.
Set 2½" x 30" alum. pipe 5" above ground with 2 ft. mound of stone with 3¼" alum cap mkd. "USDA Forest Service T21S R10W 1/4 R11W S18 RLS 1651 1984 Unlawful to Disturb". Buried brass cap and pipe alongside.