

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 100500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18; 12 & 13, T21-11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page(s) 1188)

A Cedar 48" dia., which I marked T21S S7 on NE.; R10W S18 on SE.; R11W S13 on SW.; S12 on NW. sides, with 2 notches on N. and 4 notches on S. sides, for cor. to secs. 12, 13, 18 and 7, from which

An Alder 10" dia., bears S.55½°E., 42 lks. dist. mkd. T21S R10W S18 BT.

A Cedar 24" dia., bears S.35°W., 52 lks. dist. mkd. T21S R11W S13 BT.

No other trees within limits. Raised a mound of stone, 1½ ft. high and 2 ft. base, alongside, pits impracticable.

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1057)

Intersect the old cor. of secs. 7, 12, 13 and 18, which is a Cedar 60" dia., marked and witnessed as described by the Surveyor General.

Survey by Richard Hintz - For: International Paper Co. - Nov. 1983 - M 95-40

Found Orig. 60" Cedar corner tree which is now an uproot. Set a 50d nail in the upturned roots, from which
Orig. 24" Cedar BT, now 30", bears S.35°W., 34.3 ft.
I measured to a point 12' from the center of the tree, assuming the record distance of 34.9 ft. was taken from the face, i.e. 1/2 of the original 24" dia. Cedar bearing tree.

Survey by Herman Pieske - For: U.S. Forest Service - Nov. 1984 - M 97-77 A&B

Found - Orig. 60" Cedar corner tree, now down.
49" Cedar, orig., bears S.35°W., 34.3 ft. healed blaze.
Set 5/8" x 30" Iron rod with plastic cap mkd: "AA Surveying Service Inc." in root wad at corner.
New Accessories:
10" Alder bears S.32°20'E., 19.5 ft. bark scribed "T21S R10W S18 BT"
8" Alder bears N.20°30'E., 21.4 ft. bark scribed "T21S R10W S12 BT"

(Cont. Next Page)

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 100500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 7 & 18; 12 & 13, T21-11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

17" Alder bears N.47°W., 19.2 ft. bark scribed "T21S
R11W S12 BT"
2½" x 30" alum. pipe with ¾" alum. cap mkd:
USDA Forest Service
T21S
RM
R N4°E
11 ↑ 27.9 ft.
W
S13
RLS 1651
1983
Unlawful to Disturb

Tony Hostetter - For: Roseburg Resources - 5/2024 - C.S. File
65/112-8

Found - Uprooted corner tree, out of position
60" Cedar, BT paint, record by Stuntzner, (M96-23)
S.35°W., 35.3 ft to center.
17" Alder, bark scribing visible, record by Pieske
(M97-77) S.32°20'E., 19.8 ft to center.
Calculated corner position (not set)
In stream at record distance from described BTs from which:
60" Cedar described above, bears; S.35°43'W., 35.3'
to center.
17" Alder, described above, bears; S.32°21'E., 19.8
ft to center.
Set reference monument, 3" aluminum cap, marked "LS 1975,
2024, S.01°53'E., 14.86' TO CORNER" bears;
N.01°52'50"W., 14.86'.
From RM, 16" Alder, marked "X", BT TAG, bears; N.59°E., 22.9'
to 6" spike in root collar.