

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 100540

PRIMARY CORNER DESCRIPTION WC ¼ Cor. for Sec. 7; & S. 12, T21-11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Pages 1187-88)

An Alder 12" dia., which I marked ¼ S on W. face for ¼ sec. cor., from which

An Alder 12" dia., bears S.30°W., 7 lks. dist. mkd. ¼ S BT

An Alder 3' dia., bears S.10°E., 8 lks. dist. mkd. ¼ S BT.

This corner stands in a slide, composed of logs brought down by high water; logs are piled 12 ft. deep. (July 8, 1891)

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page 1058)

(40.91 chs.)

Point for ¼ sec. cor. falls in creek.

(40.99 chs.)

Set an iron post 3 ft. long, 1' dia., 26" in the ground, for witness corner to the ¼ sec. corner, with brass cap marked:

¼
S12 | S7
WC
1919

from which

An Alder 16" dia., bears N.67°E., 86 lks. mkd. WC ¼ S7 BT

An Alder 16" dia., bears S.67°W., 44 lks. mkd. WC ¼ S12 BT

Survey by Herman Pieske, RLS #1651 - For: U.S. Forest Service Nov. 1984 - M 97-77 A&B

Set 2½" x 30" alum. pipe 22" in the ground with 24" dia. mound of stone with ¾" alum. cap mkd: "USDA Forest Service T21S R10W ¼ R11W S12 S7 1984 RLS 1651 Unlawful to Disturb".

New - 29" D.Fir bears S.81°E., 204.6 ft. scribed "¼ S7 BT"

7" Cedar bears S.34°W., 60.4 ft. scribed "¼ S12 BT"

2½" x 30" alum. pipe 26" in the ground with ¾" alum. cap mkd. "USDA Forest Service T21S R10W S7 RM N.19°40'W 50.85 ft. 1984 RLS 1651 Unlawful to Disturb", bears S.19°40'E., 50.85 ft.

Gary Smithers - Aug 2005 - C.S. File 65/54-29

Found - 1984 ¾" Alum. cap on 2½" alum pipe firmly set. We set a 6 foot galvanized steel post alongside the monument. continued next page

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 100540

PRIMARY CORNER DESCRIPTION WC ¼ Cor. for Sec. 7; & S. 12, T21-11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

14" Cedar S 340 W, 60.4 feet, with healed face, we place new tag.
38" Fir S 810 E, 204.6 feet, with healed face, we place new tag.
1984 Reference Monument 2½" Alum Pipe with ¾" Alum cap firmly set, S.19°E., 50.8 feet.
New BTs- 8" Alder, S.80°W., 7.8 ft to spike driven in side center, bark scribed "T21 R11 ¼ S12 BT", with BT tag.
Creek is N.70°E., 12.0 ft to center line & runs S.40°E.

Found: 1984 aluminum cap and accessories as described by Smithers in 2005 by T Hostetter 5/2024 - C.S. File 65/112-8