

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 & 8

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1142)

-----  
Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for  
¼ Sec. cor., with brass cap mkd:

¼  
S 7 | S 8  
1919

from which

- A Fir, 30" dia., bears N.88°E., 18 lks., mkd: ¼ S8 BT.
- A Cedar, 14" dia., bears N.63°W., 42 lks., mkd: ¼ S7 BT.

Herman Pieske RLS # 1651 - For: USFS - Nov. 1984 - M 97-74  
A&B

-----  
Found - 1" concrete filled iron pipe w/1919 GLO brass cap.  
48" D.Fir bears N.86°E., 11.9 ft. Good scar.  
20" Cedar bears N.63°W., 22.9 ft., (Rec. 27.7 ft)  
Good scar.

Set - 2½" x 30" alum. pipe at corner location, with 3¼"  
alum. cap mkd: USDA T21S R10W ¼ S7 S8 RLS 1651  
1983 UNLAWFUL TO DISTURB.  
Buried found cap alongside set monument.