

PRIMARY CORNER DESCRIPTION East 1/4 Cor. Sec. 20 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1122)

Set a hard sandstone, 24x18x6", 18" in the ground for ¼ sec. cor. of Sec. 20 only, marked ¼ on W face; from which
A Fir, 36" dia., bears S.63°W., 61 lks., mkd: ¼ S20 BT.
An Alder, 6" dia., bears N.84°W., 29 lks., mkd: ¼ S20 BT.
Iron post impracticable.

William L. Shull, LS 909 - For: USFS - Oct. 24, 1986 - C.S. File 62/30-17

Found - A weathered sandstone, 20"x8"x12", 12" out of ground, no marks, visible, but stone had clearly been set, and was not just a natural rock. (1918 Mensch GLO survey)
34" D.Fir windfall, slid down the hill, the roothole of which is approx. S.63°W., 61 links.
29" Hemlock, a Forest Service reference tree, no marks, with signs attached and painted, S.46°E., 14.9 ft., (no rec.)
Set - I replaced the stone with an alum. Forest Service monument 2½"x30" with 3¼" alum. cap marked "T21S R10W ¼ S20 1986 LS 909", set 22" deep, using the orig. stone & its remnants as a collar.
8" Hemlock bears S.25°W., 20.1 ft., scribed "¼ S20 BT" with brass washer (LS 909) Land Survey Monument sign, BT sign, and red paint.
18" Cedar, bears S.88½°W., 30.4 ft., scribed "¼ S20 BT" with brass washer (LS 909) Land Survey Monument sign, BT sign, and red paint.
Corner is on a steep (45°) North facing slope in sparse old growth timber, about 300 ft. West of FS road #4111-144.