TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 300440

PRIMARY CORNER DESCRIPTION West 1/4 Cor. Sec. 16 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Thiel under contract 342 dated Oct. 6, 1879 - (DCSO records Vol. 3 Page(s) 1012)

Set for ¼ sec. corner a rock 32x10x10, from which
A Fir, 36" dia., bears S.51°W., 19 lks.
A Cedar, 6" dia., bears N.86°E., 10 lks.

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1125)

Intersect point for old ¼ sec. cor., located by reference to the old BTs, which are marked as described by the Surveyor General. I change this cor. to refer to Sec. 16 only and at the exact cor. point set an iron post, 3 ft. long, 1" dia., 26" in the ground, for ¼ Sec. cor. for sec. 16 only, with brass cap mkd:

¼
|S 16
1919

from which
An Alder, 10" dia., bears N.54°E., 24 lks., mkd: ¼ S16 BT.
A Cedar, 18" dia., bears S.85°E., 10 lks., mkd: ¼ S16 BT.

Herman A. Pieske, RLS #1651 - For: USFS, Cooked Wassen Cadastral Survey - Aug. 1984 - M 97-33 A & B

Found - 1" iron pipe with cap broken off. (1919 survey)
24" Cedar bears N.86°E., 7.5 ft., (Orig. 18", rec. 6.6 ft) Fragmentary marks visible on partially healed face. (Rec. S.86°E.)
42" D.Fir bears S.51°W., 12.5 ft., (Orig. 36") with healed face.

Set - 2½"x30" alum. pipe, 24" in the ground, at remains of 1919 GLO corner, with 3¼" alum. cap mkd:"Dep. of Agri-Forest Service T21S R10W ¼ S16 RLS 1651 1983 UNLAWFUL TO DISTURB"
Buried 1" iron pipe alongside.