

PRIMARY CORNER DESCRIPTION East 1/4 Cor. Sec. 17 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1125)

-----  
Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for 1/4 Sec. cor. of Sec. 17 only, with brass cap mkd:

1/4  
S 17|  
1919

from which

- A Fir, 14" dia., bears S.81°W., 40 lks., mkd: 1/4 S17 BT.
- A Fir, 18" dia., bears N.69°W., 45 lks., mkd: 1/4 S17 BT.

Herman A. Pieske, RLS #1651 - For: USFS, Cooked Wassen Cadastral Survey - Aug. 1984 - M 97-33 A & B

-----  
Found - 1919 GLO iron pipe and brass cap. BC broken off & laying alongside stub of pipe.

18" D.Fir bears N.69°W., 30.4 ft. (OBT, rec. 29.7 ft) with healed face.

14" D.Fir snag bears S.79°W., 26.4 ft. (OBT, rec. S.81°W., 26.4 ft.) No marks remaining.

Set - 2 1/2"x30" alum. pipe, 24" in the ground with 3 1/4" alum. cap mkd: "US Dep. of Agri-Forest Service T21S R10W S17 RLS 1651 1983 UNLAWFUL TO DISTURB".

Set alongside remains of corner set by GLO.

38" D.Fir bears S.3°W., 29.1 ft., scribed "1/4 S17 BT"