

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 400440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William Thiel under contract 342 dated Oct. 6, 1879 - (DCSO records Vol. 3 Page(s) 1014)

Set ¼ sec. post, from which
 A Fir, 48" dia., bears N.83°W., 38 lks.
 A Fir, 16" dia., bears S.49°E., 75 lks.

Herman A. Pieske, RLS #1651 - For: Siuslaw National Forest
USDA - Dec. 1983 - M 95-80 A & B

Found - 1919 GLO brass cap, badly rusted 1" iron pipe filled with concrete, properly marked. (No record of this cap mentioned in Collier and Mensch's 1919 notes)

Set - Corner replaced w/2½"x30" alum. pipe, 24" in the ground with 3" alum. cap mkd: US Dep of Agri-Forest Service T21S R10W ¼ S15 S16 1983 RLS 1651 Unlawful to Disturb" Buried GLO monument north of new pipe.

New BTs- 17" Cedar bears S.50°W., 34.6 ft., faced and scribed: ¼ S16 BT.
30" Cedar bears S.80°E., 3.7 ft., faced and scribed: ¼ S15 BT.