

PRIMARY CORNER DESCRIPTION Cor. Secs. 9, 10, 15, & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars under contract #202, dated March 11, 1874 - (DCSO records Vol. 3 Page(s) 1010-11)

-----

Set stone, 18x9x7", 8" in ground for the corner to secs. 9, 10, 15, & 16, from which

A Hemlock, 12" dia., bears S.33°E., 19 lks.

A Hemlock, 14" dia., bears S.40°W., 20 lks.

No tree near to the North.

GLO survey by William Thiel under contract 342 dated Oct. 6, 1879 - (DCSO records Vol. 3 Page(s) 1013)

-----

(From the corner to secs. 9, 10, 15, & 16) Being a stone 18x9x7, from which

A Hemlock, 12" dia., bears S.33°E., 19 lks.

A Hemlock, 14" dia., bears S.40°W., 20 lks.

in accordance with your field notes.

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1113)

-----

Intersect the old cor. of secs. 9, 10, 15, & 16, which is a sandstone, firmly set, marked & witnessed as described by the Surveyor General, except the old SW BT is dead. Alongside, the old stone set an iron post, 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 9, 10, 15, & 16, with brass cap marked:

T21S R10W	
S 9	S 10
S 16	S 15
1919	

from which

An Alder, 12" dia., bears N.68°E., 80 lks., mkd: T21S R10W S10 BT.

A Hemlock, 24" dia., bears S.73°E., 19 lks., mkd: T21S R10W S15 BT. (Old BT)

An Alder, 8" dia., bears S.33°W., 26 lks., mkd: T21S R10W S16 BT.

A Hemlock, 24" dia., bears N.23°W., 36 lks., mkd: T21S R10W S9 BT.

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Cor. Secs. 9, 10, 15, 7 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Gary Langlitz - Stephen J. Flause - 9/13/1977 - C.S. File 59/40-10

-----

Found - Orig. stone, a sandstone, firmly set, extending 10" above ground with 4 notches on the south edge, and 3 notches on the east edge.  
Badly rusted 2" I.P., loosely set, extending 16" above ground, with brass cap attached, marked US General Land Office Survey T21S R10W S9 S10 S16 S15 1918 (Rec. 1919)  
Orig. 12" Hemlock, now 38" bears S.73°E., 12.5 ft., (Rec. S.33°E., 12.5 ft.) and (Rec. 1919 resurvey S.73°E., 12.5 ft.) with illegible 1919 rescribe marks visible on partially healed blaze which faces approx. N.30°W.  
From 1919 resurvey, a rotting Alder root shell bears N.68°E., 52.8 ft.  
SW BT is gone.  
A 24" Hemlock, now 38" bears N.23°W., 23.8 ft., with illegible scribe marks on partially healed blaze.

Set - A 1"x30" I.P., 26" in the ground, with brass cap, mkd: DOUGLAS COUNTY SURVEYOR T21S S9 S10 S16 S15 R10W 1977.  
GLO brass cap and stone alongside.

New BTs- A 12" Hemlock bears S.18°W., 19.4 ft., with double blaze and scribe mkd: T21S R10W S16 CS BT