

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars under contract #202, dated March 11, 1874 - (DCSO records Vol. 3 Page(s) 1011)

Set Fir post, 36" long, 5" dia., 20" in ground for the 1/4 sec. corner, from which
An Alder, 24" dia., bears N.10°E., 32 lks.
A Fir, 50" dia., bears N.82°W., 98 lks.

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1114)

Intersect the point for old 1/4 sec. cor., located by corner point set an iron post, 3 ft. long, 1" dia., 26" in the ground, for 1/4 sec. cor., with brass cap mkd:

1/4
S 9 | S 10
1919

from which

An Alder, 24" dia., bears N.10°E., 32 lks., mkd: 1/4 S10 BT.
(Old BT)
A Chittem, 8" dia., bears N.82°W., 96 lks., mkd: 1/4 S9 BT.
(new BT)

Douglas Co. Surveyors Office - Rod Kimberling - Pete Earle - 9/13/1977 - C.S. File 59/40-9

Found - A 1" dia., IP filled with concrete, rusted & broken off 4" above ground with brass cap laying along side properly marked.

A rotted Fir snag, 50" now 62" dia., bears N.82°W., 64.7 ft. with no remaining evidence of blaze.

A 30" dia., Alder bears N.6°E., 34.1 ft., (Rec. N.6°W., 32.6 ft.) barked scribed "1/4 BT"

Set - A 1"x30" IP w/brass cap set 8" above ground stamped:
COUNTY SURVEYORS OFFICE

T21S
1/4
S9 S10
1977

Placed orig. BC at ground level on North edge of cap. Set orig. broken IP on S. edge of brass cap.

New BO - A 5/8" rebar with alum. cap set 6" above ground, stamped "BO No. 1" bears S.35°W., 10.0 ft.

New BT - 28" dia., Alder bears N.61°W., 43.7 ft. bark scribed "1/4 S9 CS BT"