

PRIMARY CORNER DESCRIPTION West 1/4 Cor. Sec. 3 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1117)

Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for 1/4 Sec. cor. of sec. 3 only, with brass cap mkd:

1/4
| S 3
1919

from which

A Double Fir, 40" dia., bears N.10°E., 60 lks., mkd: 1/4 S3 BT.

A Fir, 30" dia., bears S.5°E., 54 lks., mkd: 1/4 S3 BT.

Douglas Co. Surveyors Office - Karen Reed, Deputy - John Powell - Aug. 18, 1982 - C.S. File 62/1-8

Found - 1919 GLO brass cap properly marked, rusted off. IP is firmly set & brass cap is lying alongside.
Orig. 40" double Fir, now 65" (at base) with good scar, bears N.10°E., 39.6 ft.

Orig. 30" Fir, now 36" windfall with good scar, bears S.5°E., 35.6 ft., to broken off stump.

Set - At the location of the found 1" IP, I set a 1"x30" IP with brass cap attached mkd: "DOUGLAS CO. SURVEYOR T21S 1/4 S3 R10W 1982" I place remains of old pipe along west side of new pipe and bury old brass cap along south side.

New BTs- 7" Alder bark scribed: "1/4 S CS BT" bears S.42 1/2°W., 15.8 ft.

1/2" Iron rod protruding 3 ft. out of ground with International Paper Co. property line sign bears N.10°E., 3.0 ft.

Note - 1/4 Corner sec. 4 bears S.3°W., 69.7 ft.