

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William Thiel under contract 342 dated Oct. 6, 1879 - (DCSO records Vol. 3 Page(s) 1016)

-----  
1/4 sec. post, is a Fir, 15" dia., from which  
A Fir, 12" dia., bears N.78°E., 19 lks.  
A Fir, 12" dia., bears S.50°E., 24 lks.

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1111)

-----  
Intersect the old 1/4 sec. cor., which is a Fir tree, marked and witnessed as described by the Surveyor General. At foot of tree set an iron post, 3 ft. long, 1" dia., 26" in the ground, for 1/4 sec. corner, with brass cap mkd:

1/4  $\frac{S\ 15}{S\ 22}$   
1919

Herman A. Pieske, RLS #1651 - For: Siuslaw National Forest  
USDA - Dec. 1983 - M 95-80 A & B

-----  
Found - 24" orig. corner tree with 1" iron pipe with 2 1/2" brass cap on SW side of tree, properly mkd. 1918  
16" D.Fir, partially knocked over, bears S.50°E., 15.8 ft., healed scar.  
Set - 2 1/2"x30" alum. pipe as reference monument, 24" in the ground bears S.45°W., 4.0 ft., from corner tree, with 3 1/4" brass cap mkd: US Dep of Agri-Forest Service RM T21S R10W 1/4 S15 S22 N.45°E. 4.0 ft. 1983 RLS 1651 Unlawful to Disturb"  
New BTs- 12" Alder bears N.62°E., 57.0 ft. bark scribed "1/4 S15 BT".  
14" Hemlock bears S.17°W., 24.1 ft. blazed and scribed "1/4 S22 BT"

Fd. Ok by Les Roberts 12/1991, M114-28 & C.S. File 63/138-1