

PRIMARY CORNER DESCRIPTION Cor. Secs. 15 & 22 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William Thiel under contract 342 dated Oct. 6, 1879 - (DCSO records Vol. 3 Page(s) 1017)

Set post in a rough gulch, filled with fallen timber, for corner to secs. 14, 15, 22, & 23, from which:

- A Cedar, 48" dia., bears N.56½°W., 50 lks.
 - A Cedar, 60" dia., bears S.27°E., 66 lks.
 - A Double Cedar, 30" dia., bears N.44°E., 59 lks.
- No tree SW near.

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1088-9)

Intersect the point for old cor. of secs. 14, 15, 22, & 23, located by reference to the old BTs, which are as described by the Surveyor General. I obliterate marks on the NE & SE BTs & at the exact cor. point set an iron post, 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 15 & 22, with brass cap mkd:

T21S|
S 15|
S 22|
R10W|
1919

from which

- A Cedar, 48" dia., bears S.68°W., 53 lks., mkd: T21S R10W S22 BT. (New BT)
- A Cedar, 48" dia., bears N.56°W., 50 lks., mkd: T21S R10W S15 BT. (Old BT)

Herman A. Pieske, RLS #1651 - For: Siuslaw National Forest USDA - Dec. 1983 - M 95-80 A & B

Found - 60" Cedar bears N.44°E., 38.9 ft. to face, healed.
60" Cedar bears N.56°W., 33.0 ft., to face, healed.
Corner position falls in a recent active slide area.

Set - Witness corner 52.35 ft. West of corner on line.
2½"x30" alum. pipe, 24" in the ground, with ¾" alum. cap mkd: US Dep of Agri-Forest Service T21S R10W WC S15 S22 RLS 1651 1983 Unlawful to Disturb.
18" Hemlock bears N.50°W., 27.6 ft., scribed: WC T21S R10W S15 BT.
24" Hemlock bears S.32°E., 41.0 ft., faced & scribed: WC T21S R10W S22 BT.