

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Cor Secs 14 & 23 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1089)

Set an iron post, 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 14 & 23, with brass cap mkd:

T21S	
S 14	
S 23	

from which

- A Hemlock, 6" dia., bears N.55°E., 13 lks., mkd: T21S R10W S14 BT.
- A Fir, 36" dia., bears S.78°E., 18 lks., mkd: T21S R10W S23 BT.

Herman A. Pieske, RLS #1651 - For: Siuslaw National Forest USDA - Dec. 1983 - M 95-80 A & B

Found - 2" rusted pipe & concrete stem with 1919 GL0 brass cap, broken off alongside pipe, properly marked.
14" Hemlock bears N.57°E., 8.7 ft., healed face.
34" D.Fir bears S.33°E., 10.8 ft., healed face.

Set - At location of GL0 pipe, set 2½"x30" alum. pipe, 24" in the ground, with 3¼" alum. cap mkd: US Dep of Agri-Forest Service T21S R10W S14 S23 RLS 1651 1983 Unlawful to Disturb.