

PRIMARY CORNER DESCRIPTION Cor. Secs. 10 & 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William Thiel under contract 342 dated Oct. 6, 1879 - (DCSO records Vol. 3 Page(s) 1020)

Set post to corner of Secs. 14, 15, 10 & 11, form which:

- An Alder, 8" dia., bears S.77°W., 60 lks.
- A Cedar, 12" dia., bears N.22°W., 34 lks.
- A Cedar, 8" dia., bears N.1°E., 21 lks.
- A Cedar, 12" dia., bears S.10°E., 59 lks.

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1092)

Intersect the point for cor. of secs. 10, 11, 14, & 15, located by reference to the old BTs, which are marked as described by the Surveyor General, except the SW tree has fallen. I obliterate marks on the NE & SE BTs and at the exact cor. point set an iron post, 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 10 & 15, with brass cap mkd:

	T21S	
¼	S 10	
	S 15	
	1919	

from which

- A Maple, 10" dia., bears S.25°W., 62 lks., mkd: T21S R10W S15 BT. (New BT)
- A Cedar, 18" dia., bears N.22°W., 34 lks., mkd: T21S R10W S10 BT. (Old BT)

Tom McCullough, LS #650 - 1970 - C.S. File 58/290-2

Found - No monument found.

- 14" Maple bears S.25°W., 40.8 ft., face grown over. 1918
- 24" Cedar bears N.22°W., 22.4 ft., face chopped out scribing visible. 1918

Set - 2"X30" iron pipe with brass cap mkd:

	T21S	R10W	
	10		
	15		14
	1970		
	650		

2 fence posts with signs ±5 ft. facing West and ± 5 ft. facing North.

continued next page

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 500470

PRIMARY CORNER DESCRIPTION Cor. Secs. 10 & 15

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

E R Alvarado, USFS Surveyor - Witness: M Peterson - 8/26/1982
(filed 3/12/1984 & **added to record 11/7/2018**) - C.S. File
62/15-15

Found - Brass cap on 1¼" pipe approx 2' out of ground, cap
(properly) mkd
25" Cedar bears N.22°W., 21.0', face chopped out,
scribing visible.
20" Maple, bears S.40°W., (rec. S.25°W.) 40.7', face
grown over.
New - BTs painted with 6" red bands and blazes. Area
flagged with pink "Land Line" ribbon"
Note - Magnetic decl. is 20°E.
Distances are to side and center of trees at root
crown.
Go approx. 3.5 mi. on rd. 110 to rd. 111. Location
poster at end of 111. From location poster, cor.
lies S.56°E., 700'. Corner can be seen from
landing on road 111 on SE corner of clearcut.
Attention sign on metal post next to cap.