

PRIMARY CORNER DESCRIPTION Cor. Secs. 2 & 11 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1096)

Set an iron post, 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 2 & 11, with brass cap mkd:

T21S
|S 2
|S 11
|R10W
1919

from which

A Fir, 24" dia., bears N.33°E., 25 lks., mkd: T21S R10W S2 BT.

An Alder, 12" dia., bears S.71°E., 43 lks., mkd: T21S R10W S11 BT.

Douglas Co. Surveyors Office - John Powell - Frank Jones - W. Penley - 10/2/1969 - C.S. File 54/1-39

Found - GLO brass cap set in 1919, cap rusted away.
24" now 38" D.Fir, N.33°E., 16.5 ft., shows good scar.

12" Alder, now dead, S.71°E., 28.4 ft.

Set - Brass cap at cor. mkd: COUNTY SURVEYOR'S T21S R10W OFFICE, 1969

S 3 |S 2
|S 11

16" Cedar S.29°E., 29.7 ft., mkd: T21S R10W S11 CS BT.