

PRIMARY CORNER DESCRIPTION S. 1/4 Cor. for S. 35 only, T20-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Nathaniel Martin, under Contract 599, dated June 20, 1892 - (DCSO records Vol. 1 Page(s) 209)

Set post 4 ft. long, 3½" sq., 24" in the ground for ¼ sec. cor. marked ¼ S on N. face; from which

A Fir 60" dia., bears S.24°W., 69 lks. dist. mkd. ¼ S BT
Alder 5" dia., bears N.46½°W. 67 lks. dist. mkd. ¼ S BT.

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (Group #36) (surveyed 1919) - (DCSO records Vol. 1 Page(s) 257-58) and Dup. Pgs. 1062-63)

Intersect the point for ¼ sec. cor., located by reference to the old SW. bearing tree. I obliterate marks on this tree and at the exact cor. point, Set an iron post 3 ft. long, 1" dia., 26" in the ground for ¼ sec. cor. of sec. 35 only, with brass cap mkd: ¼ $\frac{S35}{1919}$

from which

An Alder 10" dia., bears N.62°E., 21 lks. dist. mkd. ¼ S35 BT.

A Wild Cherry 10" dia., bears N.9°W., 55 lks. dist. mkd. ¼ S35 BT.

BLM resurvey by Thomas A. Tillman, Cadastral Surveyor, under Group #297, Surveyed May 1951/Oct. 1952 - (DCSO records Vol. 27 Page(s) 11667-68)

The ¼ sec. cor., monumented with an iron post 1" dia., 8" above ground, firmly set, with brass cap mkd. in 1918, from which the 1918 bearing trees:

An Alder 16" dia., bears N.62°E., 21 lks. dist., with illegible scribe marks visible on decayed blaze.

A dead and down Cherry, 12" dia., bears N.9°W., 55 lks. dist., with no scribe marks remaining on decayed blaze.

The iron post is rusted nearly through; in its place Set an iron post 3 ft. long, 1" dia., 28" in the ground with brass cap mkd: ¼ S 35

1951

from which new bearing trees:

A Hemlock 20" dia., N.45¼°E., 69 lks. dist. mkd. ¼ S35 BT.

A Hemlock 24" dia., N.54¼°W, 140 lks. dist., mkd. ¼ S35 BT
Deposit the old iron post at the base of the new iron post.

(Cont. Next Page)

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 539700

PRIMARY CORNER DESCRIPTION S. 1/4 Cor. for S. 35 only, T20-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
May 1968 - C.S. File 54/1-11

Found - No trace of brass cap, but 1951 BTs, as follows:
20" now 24" Hemlock, alive, N.45¼°E., 45.5 ft.,
scribe marks visible on nearly healed blaze.
24" now 26" Hemlock, alive, N.54¼°W., 92.4 ft.,
scribe marks visible on partially healed blaze.

Set brass cap at cor. mkd: County Surveyors office

T20S R10W ¼ S 35
T21S 1968

Set 6 ft. steel fence post alongside brass cap.
The ¼ Cor. of sec. 2, T21-10, bears S.87 3/4°E., 13.9 ft. &
14 ft. W. of new logging road, course N.30°W & S.30°E.

Fd Ok by DCSO 2/1970 C.S. File 54/1-20A (added 3/18/2019)
C.S. brass cap on edge of roadway & BTs in good condition