

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Cor. Secs 1, 2, 11, & 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1080-1)

Set an iron post, 3 ft. long, 2" dia., 24" in the ground, for cor. of secs. 1, 2, 11, & 12, with brass cap mkd:
T21S R10W
S 2 | S 1
S 11 | S 12

from which
An Alder, 16" dia., bears N.44°E., 13 lks., mkd: T21S R10W S1 BT.
An Alder, 12" dia., bears S.52°E., 13 lks., mkd: T21S R10W S12 BT.
An Alder, 12" dia., bears S.32°W., 21 lks., mkd: T21S R10W S11 BT.
An Alder, 8" dia., bears N.65°W., 22 lks., mkd: T21S R10W S2 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - Mar. 1967 - C.S. File 54/1-37

Found - 1919 GLO brass cap with pipe broken off at ground level, 17" down & from top, & 1919 BTs:
16" now 18" Alder, almost dead, face rotted away, no scribe, N.44¼°E., 8.6 ft.
12" now 14" Alder, 20 ft. high snag, S.52°E., 8.6 ft., frag scribe marks on unhealed blaze.
12" now 15" Alder, nearly dead, S.32°W., 13.9 ft., unhealed blaze, face rotted, no scribe.
No trace of NW BT.

Set - Brass cap at cor. mkd: COUNTY SURVEYORS T21S R10W
(Set in place of OFFICE 1967 S 2 | S 1
old IP) S 11 | S 12

New BTs- 10" Hemlock N.13°E. 15.1 ft. mkd: T21S R10W S1 CS BT
14" Hemlock S.79°E., 25.6 ft., mkd: T21S R10W S12 CS BT.
8" Hemlock S.10°W., 36.7 ft., mkd: T21S R10W S11 CS BT.
15" Hemlock N.84°W. 25.2 ft. mkd: T21S R10W S2 CS BT

Note - This corner lies approx. 150 ft. West of Rd. #217. Reset old brass alongside.

Tom McCullough, April 1970, set 1 fence post ±5 ft. north facing east. C.S. File 55/148

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 600600

PRIMARY CORNER DESCRIPTION Cor Secs 1, 2, 11, & 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Ernesto R. Alvarado, USFS & Dep. Doug. Co. Surveyor - Colin Long, Survey Tech. Witness - Aug. 21, 1981 - C.S. 61/27-33

Found - Douglas Co. BC, properly marked, in good condition. 12" rotted Alder stump bears N.40°E., 8.4 ft., no scribing. 1919 Orig.
Rotted Hemlock stump with broken snag lying 5 ft. down the hill will scribing: T21S R10W S1 CS BT bears N.12°E., 14.9 ft.
12" rotted Hemlock stump bears S.79°E. 25.4 ft. 1967
No trace of 1919 NW, SE, & SW BTs.
No trace of 1967 NW & SW BTs.
New BTs- 4" D.Fir bears N.9°E., 15.6 ft., with blazed X at breast height & on lower blaze scribed CS BT.
No other trees large enough to mark.
Note - Attention & property boundary signs placed on 6 ft. steel fence post North of corner. Attention sign on fence post placed South of corner. Painted 6" red bands & blazes on all BTs. Area flagged with pink "Land Line" ribbon. Distances are to side and center of trees at root crown.
Location -
From Smith River road, take FS Rd. #110 approx. 2.2 miles to location poster on sec. line post on East side of road. From post, go S.0°17'41"E., 324.6 ft. Corner lies on SW slope.

Jerry Estabrook - For: Roseburg Resources - 1/2022 - M180-48

Found - A 1" iron pipe with 2½" brass cap (properly) marked. Set steel post alongside
A 19" Fir with healed face and tag bears N.9°E., 15.6'.
A 26" Fir with healed face and tag bears S.76°45'W., 8.1', No record.
A Steel fence post bears North 5.0'.
A steel fence post bears West 1.0'.
New BTs- A 17" Fir, face scribed "NW S12 BT" with X- chop and tag bears S.73°E., 22.2' to a spike at side center.
A 20" Fir, face scribed "SW S2 BT" with X- chop and tag bears N.38°W., 37.5' to a spike at side center.
Lat and Long per GARMIN ETREX hand held GPS:
N: 43°46'09.5" W: 123°50'56.6"