

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 600640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 2

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1082-3)

Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for 1/4 Sec. cor., with brass cap mkd:

1/4
S 2 | S 1
1919

from which

An Alder, 18" dia., bears N.74°E., 44 lks., mkd: 1/4 S1 BT.

An Alder, 24" dia., bears N.24°W., 36 lks., mkd: 1/4 S2 BT.

Douglas Co. Surveyors Office - Gary L. Langlitz - Clell E. Goodwin - A. Vic Cangie - M. Lenora Ladig - 11/12/1975 - C.S. File 57/39-9

Found - Remains of 1" concrete filled IP with brass cap, 1919, properly stamped, from which Orig. 24" now 26" Alder BT bears N.24°W., 23.8 ft. Nothing remains of the orig. NE BT.

Set - Brass cap on a 1 1/2" x 30" IP stamped:

DOUGLAS COUNTY SURVEYOR

T21S R10W
1/4 S 2 | S 1
1975

We replace the remains of old pipe beside corner.

22" Hemlock scribed "1/4 S2 CS BT" in a single blaze bears S.75 1/2°W., 47.4 ft.

12" Hemlock scribed "1/4 S1 CS BT" in a double blaze bears N.49°E., 50.3 ft.

Compass declination 20°E

Ernesto R. Alvarado, USFS & Dep. Doug. Co. Surveyor - Carol Dickison, Witness - Aug. 13, 1981 - C.S. File 61/27-32

Found - Douglas Co. Surveyors cap 6" above ground, solid, leans slightly to West, properly marked.

1" concrete filled iron pipe, badly rusted, in ground, 0.3 ft. south of cap (pipe was for 1919 BC)

27" Alder bears N.24°W., 23.7 ft., open blaze, face rotted w/faint scribing visible, 1919 BT.

continued next page

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 600640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 1 & 2

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Broken remains of low cut Hemlock stump, bears N.49°E., 50.3 ft. scribing visible on broken piece of wood (still attached) 1975
23" Hemlock bears S.76°W., 47.2 ft., open face, scribing visible: ¼ S2 CS BT.
New - Re-scribed 27" Alder (bark scribed): ¼ S2 CS BT alongside old face. (1919 NW BT)
Note - Distances are to side & center of trees @ root crown
Location -
From sec. line poster on East side of road go N.0°17'41"W., 2312.5 ft. Follow old fire trail. ¼ cor. is on tree line on small bench West of N landing in unit.

Jerry Estabrook - For: Roseburg Resources - 1/2022 - M180-48

Found - A 1½" iron pipe with 2½" brass cap (properly) marked with 1919 GLO 1" iron pipe bearing South 0.3'. Set steel post alongside
A 38" Hemlock with healed face and tag bears S.76°W. 47.2'
A 29" Alder w/healed face & tag bears N.24°W., 23.7'
New BTs- An 18" Fir, face scribed "W¼ S1 BT" with X-chop and tag bears N.50°E., 22.9' to a spike at side center
A 14" Fir, face scribed "E¼ S2 BT" with X-chop and tag bears S.2°W., 10.2' T0 to a spike at side center.
Lat and Long per GARMIN ETREX hand held GPS:
N: 43°46'35.6" W: 123°50'56.5"