

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 646100

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 1 only, T22-10

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Aurelius Todd, Deputy Surveyor, under Contract #629, dated April 24, 1894 - (DCSO records Vol. 4 Pg 1749)

-----  
Set a Post 4 ft. long, 4" sq., 24" in the ground mkd.  $\frac{1}{4}$  S. on N. face for  $\frac{1}{4}$  sec. cor., from which,  
A Fir 20" dia., bears N.33°E., 34 lks. dist. mkd.  $\frac{1}{4}$  S BT.  
A Fir 10" dia., bears S.70°W., 130 lks. dist. mkd.  $\frac{1}{4}$  S BT.

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1038)

-----  
The old  $\frac{1}{4}$  sec. cor., which is a decayed post, mkd. and witnessed as described by the Surveyor General. The old bearing trees are dead. Alongside the old cor., Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for the  $\frac{1}{4}$  sec. cor. of sec. 1 only, with brass cap mkd:

$\frac{1}{4}$  S1  
1919

from which

A Fir 8" dia., bears S.11°E., 44 lks. dist. mkd.  $\frac{1}{4}$  S1 BT.  
(New BT)  
A Fir 8" dia., bears S.35°W., 40 lks. dist. mkd.  $\frac{1}{4}$  S1 BT.  
(New BT)

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, V. Perron, crew - May 1968 - C.S. File 54/1-7

-----  
Found - 1919 GLO brass cap in place. Pipe badly rusted.  
Orig. 8" now 22" Fir, alive, S.11°E., 29.0 ft., shows good scar.  
Orig. 8" now 10" Fir, decayed remains of stump only, S.35°W., 26.4 ft., find partial old blaze and reverse scribe in stump.

Set Brass cap at cor. mkd: County Surveyors Office

T 21 S  
T 22 S R10W  $\frac{1}{4}$  S 1  
1968

New BTs -18" D.Fir S.60°E., 25.8 ft. mkd.  $\frac{1}{4}$  S1 CS BT.  
14" Alder S.49°W., 18.1 ft. mkd.  $\frac{1}{4}$  S1 CS BT.

Deposit old corner pipe and brass cap alongside. This corner lies on moderate S. slope approx. 348 ft. N.88°E. of  $\frac{1}{4}$  Sec. 36, T21-10.

continued next page

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 646100

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 1 only, T22-10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Tony Hostetter - For: Roseburg Resources - Jan. 2020 - C.S.  
File 65/105-10

-----

Found - 1968 DCSO brass cap from which:  
28" Fir, face evident, bears; S.60°E., 25.8 ft to center.  
20" Fir snag, face evident, BT tag, bears; S.11°E., 29.0 ft to center.  
New BTs- 11" Fir, marked "X", BT tag, bears; N.19°E., 22.3 ft to spike.  
20" Fir, marked "X", BT tag, bears; S.26°W., 35.7 ft to spike.