

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30 & 31 only, T21-9

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608 -dated April 17, 1893 - (DCSO records Vol. 2 Page(s) 903)

-----  
Set Cedar post 5 ft. long, 6" sq., 24" in the ground on steep hill side sloping NW. for cor. to secs. 30, 31, 25 and 36, marked T21S S30 on the NE.; R9W S31 on the SE.; R1W S36 on the SW.; and S25 on the NW. faces, with 1 notch on the S. and 15 notches on the N. edges, from which

- A Cedar 18" dia., bears N.28°30'E., 73 lks. dist. mkd. T21S R9W S30 BT.
- A Cedar 26" dia., bears S.17°E., 80 lks. dist. mkd. T21S R9W S31 BT.
- A Cedar 26" dia., bears S.43°15'W., 67 lks. dist. mkd. T21S R10W S36 BT.
- A Cedar 18" dia., bears N.60°45'W., 22 lks. dist. mkd. T21S R10W S25 BT.

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 988) and (Dup. Pg. 1024)

-----  
Intersect the old cor. of secs. 25, 30, 31 and 36, which is a decayed stake, marked and witnessed as described by the surveyor general. I obliterate marks on the SW. and NW. bearing trees and change this cor. to refer to secs. 30 and 31 only. Alongside the old cor., Set an iron post 3 ft. long, 2" dia., 24" in the ground for cor. of secs. 30 & 31 only, with brass cap mkd:

T21S  
S 30  
S 31  
R9W  
1919

from which

- A Cedar 16" dia., bears N.30°E., 75 lks. dist. mkd. T21S R9W S30 BT. (Old BT)
- A Cedar 24" dia., bears S.20°E., 66 lks. dist. mkd. T21S R9W S31 BT. (Old BT)