

TOWNSHIP 21 RANGE 10 POINT IDENTIFIER # 700216

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 30 only, T21-9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608 -dated April 17, 1893 - (DCSO records Vol. 2 Page(s) 904)

-----  
Set Maple post 4 ft. long, 4" sq., 24" in the ground on hill side sloping S. for 1/4 sec. cor. marked 1/4 S on the W. face, from which  
A Fir 34" dia., bears N.75°30'E., 33 lks. dist. mkd. 1/4 S BT.  
An Alder 8" dia., bears S.76°W., 39 lks. dist. mkd. 1/4 S BT.

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 989-90) and (Dup. Pg. 1025)

-----  
Intersect the point for old 1/4 sec. cor., located by reference to the old bearing trees, which are as described by the surveyor general. I obliterate marks on the old SW. bearing tree and at the exact cor. point, Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for 1/4 sec. cor. of sec. 30 only, with brass cap marked  
1/4  
| S 30  
1919

from which  
A Fir 34" dia., bears N.75°30'E., 33 lks. dist. mkd. 1/4 S30 BT (Old BT)  
A Fir 58" dia., bears S.20°E., 27 ks. dist. mkd. 1/4 S30 BT (New BT)

Douglas Co. Surveyors Office - John M. Powell, and crew - March 28, 1973 - C.S. File 56/25-6

-----  
Found - 1919 GLO brass cap, broken off.  
34" D.Fir, now stump, N.75 1/2°E., 21.8 ft., shows good scar.  
58" D.Fir, now down, S.20°E., 17.8 ft., shows scar.  
Set brass cap along side old pipe mkd:  
County Surveyors Office  
T 21 S  
R | R  
10 1/4 | S30 9  
W | 1973 W

New BTs- 7" D.Fir N.60°E., 5.0 ft., scribed 1/4 S30 CS BT.  
22" Hemlock S.62°W., 25.0 ft. scribed 1/4 CS BT.  
(Cont. Next Page)

