

PRIMARY CORNER DESCRIPTION M.C. on W. bdy. Sec. 32

Alias <u>891220</u>	Description <u>M.C. Right bank Umpqua River</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 3 Page(s) 1181)

Set post, from which
An Alder 8" dia., bears N.38°E., 71 lks. dist.
An Ash 8" dia., bears N.79½°W., 88 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page(s) 1242-43)

Replace the meander post on right bank of Umpqua River, to fractional secs. 31 and 32, by setting a post, 4 ft. long, 4" sq., 24" in the ground, marked M C on S. face, with T21S on N.; R11W S32 on S.; S31 on W. faces, from which
An Alder 8" dia., bears N.38°E., 71 lks. dist. mkd. T21S R11W S32 M C BT.
An Ash 8" dia., bears N.79½°W., 88 lks. dist. mkd. T21S R11W S31 M C BT.
I also raised a mound of stone, 1½ ft. high and 2 ft. base alongside.

Survey by Ronald Stuntzner - For: Moore Mill & Lumber Co. - June 20, 1979 - M 78-79

Set 5/8" Iron rod, from which
14" D.Fir bears S.55°W., 16.8 ft.
12" D.Fir bears N.87°E., 40.7 ft.
Note - This survey was superceded by M 97-16.

Surveyed by Ronald Stuntzner - For: Moore Mill & Lumber Co. -April, 1984 - M 97-16

Note - This Survey is to amend perevious survey M 78-79.
Set - 5/8" x 30" iron rod w/plastic I.D. cap mkd: "Stuntzner Engineering". Proportioned Meander corner, no evidence or original corner found, corner falls approx. 400' east of gulch on fir covered ridge.
Accessories -
12" D.Fir bears S.78½°E., 71.5 ft. (healed 1979 BT)
14" D.Fir bears N.85°W., 31.7 ft. (scribed MC BT)
Note - Previously monumented position bears N.61°40'44"W., 33.52 ft.

Corner found and used in BLM resurvey by Deborah M. Stephens and Harvey E. Wofford. Surveyed April 1990 thru April 1995 under group #1521. (DCSO records Vol. 51 Page(s) 19610)

