

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 200440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 & 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John W. Meldrum, Deputy surveyor, under Contract #116, dated December 16, 1866 (DCSO records Vol. 3 Page(s) 1155)

Set post for ¼ sec. cor., from which
A Cedar 10" dia., bears N.5°W., 34 lks. dist.
A Cedar 20" dia., bears S.55°E., 10 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page(s) 1246 and 1247)

(Page 1246)
Having been informed by settler Pyritz, that he has sought repeatedly after the ¼ sec. cor. bet. secs. 17 and 18, but without result.
(Page 1247)
(At 40 chs. and 2.40 chs. W. of true corner) a Fir 16" dia., with ¼ S W C on W. face, from which
A Fir 42" dia., bears S.27°W., 11 lks. dist. mkd. ¼ S WC BT.
A Fir 36" dia., bears N.58°E., 25 lks. dist. mkd. ¼ S WC BT.

Survey by Harry S. Hugill - For: Walter A Pyritz - Jan. 15, 1949 - C.S. File 40/169

Set 1½" Iron pipe by proportional measurements.
Point on W. side of canyon, above bare rock outcrop and 75.0 ft. West of creek.
8" Alder bears S.18°W., 11.5 ft.
6" Alder bears N.20°E., 10.0 ft.

Douglas Co. Surveyors Office - Gary L. Langlitz, Deputy - V. Cangie; J. Nordling, crew - Jan. 13, 1975 - C.S. File 57/17-5

Found - 1½" I.Pipe firmly set and in good condition.
An 8" now 12" Alder mkd. by Hugill, bears S.18°W., 11.5 ft., alive and well healed.
We find no identifiable remains of Hugill's NE BT.
We leave the corner monument intact and mark the following
BT: A 12" Red Cedar bears S.75°E., 38.8 ft. scribed "¼ 17 CS BT".

Fd. OK, Nov. 1982 by R. Geisler - M 93-34