

PRIMARY CORNER DESCRIPTION Sec Cor for 7, 8, 17 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John W. Meldrum, Deputy surveyor, under Contract #116, dated December 16, 1866 (DCSO records Vol. 3 Page(s) 1155)

Set post for cor. to secs. 7, 8, 17 and 18, from which
An Alder 25" dia., bears S.20°W., 24 lks. dist.
An Alder 10" dia., bears S.15°E., 36 lks. dist.
An Alder 30" dia., bears N.50°W., 54 lks. dist.
An Alder 10" dia., bears N.45°E., 8 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page(s) 1247)

Set a post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 7, 8, 17 and 18, marked T21S S8 on NE.; R11W S17 on SE.; S18 on SW.; S7 on NW. faces, with 4 notches on S. and 5 notches on E. edges, from which
A Fir 30" dia., bears N.45°E., 45 lks. dist. mkd. T21S R11W S8 BT.
A Fir 36" dia., bears S.53°E., 13 lks. dist. mkd. T21S R11W S17 BT.
A Fir 16" dia., bears S.66°W., 28 lks. dist. mkd. T21S R11W S18 BT.
A Fir 36" dia., bears N.25°W., 41 lks. dist. mkd. T21S R11W S7 BT.

The remains of Alders lying close by, which were probably the bearing trees of former survey.

Douglas Co. Surveyors Office - Bruce R. Rogers, Mike Stone, crew - June 1965 - C.S. File 53/66-133

Found - Orig. 36" Fir now 44", N.25°W., 27.1 ft., chopped out to good face, shows scribing (straight lines)
Orig. 30" Fir now 40", N.45°E., 29.7 ft., shows good scar, did not open.
Orig. 16" Fir, now rotten stump.
1½" Iron pipe at corner with cap mkd:

S 7	S 8
S18	S17

Fd. OK July 1982 - M 93-10

Survey by Ronald G. Geisler, LS 1988 - For: Champion International Corp. - Nov. 1982 - C.S. File 58/278 and M 93-34

Found - 46" Fir bears N.25°W., 29.8 ft. (Rec. 27.1 ft.)
Chopped face with marks visible. (1891)
(Cont. Next Page)

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 200500

PRIMARY CORNER DESCRIPTION Sec Cor for 7, 8, 17 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

48" Fir bears N.42°E., 25.8 ft. (Rec. N.45°E., 29.7 ft.) Scar visible. (1891)
19" rotten Fir stump bears S.72°W., (Rec. S.66°W.) 18.4 ft. (1891)
Replaced a leaning 1½" x 54" I.P., plugged at top, with brass cap and iron pipe. Placed the I.P. upside down and 0.3 ft. North of the cap. Date set unknown.
New BTs -16" Fir bears S.41°E., 49.1 ft. scribed T21S R11W S17 BT.
24" Fir bears S.82°W., 40.8 ft. scribed T21S R11W S18 BT.

Fd ok by R. Ward - 12/3/1984 - C.S. 58/146-011

Jerry Estabrook - 9/26/2015 - C.S. File 65/89-57

Found - A 2½" brass cap on 2" iron pipe marked "T21S R11W S7 S8 S17 S18 1982 PLS1988" per M93-34.
A rotten fir stump with tags bears S.41°E., 49.1'.
A rotten original fir stump with no visible marks bears S.72°W 18.4'.
A rotten fir stump with visible scribe in face and tag bears S.82°W., 40.8'.
A 46" original fir stump with burnt out face and tag bears N.25°W., 29.8'.
New - A 13" fir face scribed "NW S17 BT" with X-chop and tag bears S.46°E., 32.1' to a spike at side center.
A 12" fir face scribed "NE S18 BT" with X- Chop and tag bears S.06°W., 6.7' to a spike at side center.
An 11" fir face scribed "NE S18 BT" with X-chop and tag bears S75°W., 16.5' to a spike at side center.
Lat and Long per GARMEN ETREX hand held GPS
N 43°45'17.3" W 124°02'44.1"
Compass Declination 18° EAST