

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5, 6, 7 and 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page(s) 1249)

A Fir 16" dia., which I marked for cor. to secs. 5, 6, 7 and 8, T21S S5 on NE.; R11W S8 on SE.; S7 on SW.; S6 on NW. sides, with 5 notches on E. and S. sides, from which
A Cedar 10" dia., bears N.12½°E., 20 lks. dist. mkd. T21S R11W S5 BT.
A Cedar 9" dia., bears S.63¼°E., 17 lks. dist. mkd. T21S R11W S8 BT.
An Alder 24" dia., bears S.14½°W., 15 lks. dist. mkd. T21S R11W S7 BT.
A Fir 42" dia., bears N.21°W., 28 lks. dist. mkd. T21S R11W S6 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Jack Heritage, E. West, crew - March 1967 - C.S. File 54/1-35

Found - Stump of corner tree with fragment reverse scribing. Orig. 10" now 26" Cedar N.12½°E., 15.2 ft., 13.2 ft. face to face., shows fragmentary scribe on opened blaze. Rescribe "T21S R11W S5 CS BT".
Orig. 42" now 46" Fir stump N.21°W., 18.5 ft. face to face., shows good scar. Do not open.
No trace of other BTs.

Set Brass cap on W. side of corner tree stump mkd:
County Surveyors Office

T 21 S R 11 W
S 6 | S 5
S 7 | S 8
1967

New BTs -40" Cedar N.46½°W., 27.0 ft. mkd. T21S R11W S6 CS BT
36" Cedar S.18°W., 30.1 ft. mkd. T21S R11W S7 CS BT.
No suitable tree to SE.

This corner lies approx. 350 ft. W. of main creek, course S. on steep SE slope. State Forestry tag on 12" Alder on E. side of creek.

Douglas Co. Surveyors Office - Larry E. Monrean; Mike Tompkins, crew - Dec. 13, 1976 - C.S. File 59/26-22

Found - Badly decayed stump of orig. corner tree.
1967 DCSO brass cap, bears West, 1.3 ft. from center of orig. corner tree stump.
(Bearings and distances recorded below are from the DCSO brass cap, not the orig. corner tree stump)
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5, 6, 7 and 8

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>Orig. 10" now 26" Cedar bears N.17½°E., 14.9 ft. 1967 rescribe on open blaze "T21S R11W S5 CS BT" Orig. 42" now 46" Fir stump bears N.17½°W., 20.1 ft. Has good scar, I did not open. A 36" Cedar bears S.16½°W., 30.1 ft. Tree has open blaze, scribing visible "T21S R11W S7 CS BT" A 40" now 44" Cedar bears N.43°W., 26.2 ft. Tree has open blaze, scribing visible "S R11W S6 CS". Tree not scribed BT as recorded. To the 44" Cedar in the NW quadrant, I make a second blaze and I add scribing "BT". (Bearings and distances recorded are measured to the center of the base of the BTs.)</p>
<p>Robert Ward, Jr - For: Champion International Corp - 8/1979 - M78-76 (added 11/2015) ----- Found - Brass cap attached to an iron pipe. 40" cedar, bears N.46°30'W., 27.0' 36" cedar, bears S.18°00'W., 30.1' 26" cedar, bears N.12°30'E., 15.2' 46" Fir stump, bears N.21°00'W., 18.5'</p>
<p>Jerry Estabrook - 9/26/2015 - C.S. File 65/89-56 ----- Found - A 2½" Brass cap on 1" iron pipe marked "T21S R11W S5 S6 S7 S8 1967" along side rotten original corner tree stump per C.S. 54/1. A Rotten original cedar snag bears N.12°30'E., 15.2'. A rotten cedar stump bears N.46°30'W., 27.0'. A rotten original fir stump bears N.21°W., 18.5'. New - A 43" Fir bark scribed "SW S5 BT" with X-chop and tag bears N.21°E., 31.5' to a spike at side center. A 29" spruce face scribed "SE S6 BT" with X- chop and tag bears N.85°W., 31.0' to a spike at side center. Lat and Long per CARMEN ETREX hand held GPS N 43°46'09.2" W 124°02'43.6" Compass declination 18' east</p>
<p>Fd. 1967 DCSO cap & accessories as described by Estabrook, by T Hostetter 10/2019 - C.S. File 65/103-12</p>
<p>2</p>