

PRIMARY CORNER DESCRIPTION Sec. Cor. for 20, 21, 28 and 29

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by John W. Meldrum, Deputy surveyor, under Contract #116, dated December 16, 1866 (DCSO records Vol. 3 Page(s) 1158)

Set stone, 16x12x8 ins., on steep rocky hill side for cor. to ses. 20, 21, 28 and 29, from which
An Alder 4" dia., bears N.67°W., 38 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page(s) 1223)

Set a post, 4 ft. long, 4" sq., 24" in the ground, for cor. to secs. 20, 21, 28 and 29, marked T21S S21 on NE.; R11W S28 on SE.; S29 on SW.; S20 on NW. faces with 2 notches on S. and 4 notches on E. edges, from which
A Maple 36" dia., bears S.87½°W., 511 lks. dist. mkd. T21S R11W S29 BT.
And raised a mound of stone, 1½ ft. high and 2 ft. base alongside; pits impracticable.

BLM resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #430, Surveyed June/Aug. 1960 (DCSO records Vol. 31 Page(s) 12904)

The cor. of secs. 20, 21, 28 and 29, determined at record bearing and distance from the original bearing tree:
A Maple 63" dia., bears S.87½°W., 511 lks. dist., with a healed blaze.

At the corner point
Set an iron post 28" long, 2½" dia., 15" in the ground, to solid rock and supported in a mound of stone, 3 ft. base, to top, with brass cap mkd:
T 21 S R 11 W
S 20 | S 21
S 29 | S 28
1960

from which new bearing trees
A Fir 29" dia., bears N.1°E., 55 lks. dist., mkd. T21S R11W S21 BT.
A Cedar 10" dia., bears S.56½°E., 41 lks. dist. mkd. T21S R11W S28 BT.
A Cedar 10" dia., bears S.9°W., 66 lks. dist. mkd. T21S R11W S29 BT.
A Fir 11" dia., bears N.28½°W., 75 lks. dist. mkd. T21S R11W S20 BT.

Fd. OK Feb. 1984 by J. Prochnau - M 96-63 A & B

continued next page

Alias	Description

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Garrett McGraw - 4/12/2011 - C.S. File 67/33-30

Found - No evidence of 1866 or 1891 orig. monuments is fd. 1960 3¼" dia., BLM brass cap (properly mkd) on a 2½" I.D. 28" long iron pipe is lying loose on ground surface with out position, and near base of uprooted fir stump.

Some scattered loose stone are seen but no clear evidence of described stone mounds is found.

1891 - A maple 36" dia., now an 80" dia., breast height, Big leaf Maple with no blaze marks, and now with center burned out and a ⅓ to a ½ of the trunk broken away and fallen (tree is still living) This tree bears S.87½°W., 337.3 ft. (as per rec) our measurement is slightly longer, suggesting this may be a face measurement but due to steep terrain and large irregular shape of root crown we agree with orig. record.

1960 - A fir 11" dia., now 23" DBH D.Fir with a fully healed single blaze bears N.28½°W., 49.5 ft. (as per rec.)

1960 - A cedar 10" dia., now a fallen and rotted 14" dia., 5 ft. long cedar stump with a partially healed single blaze showing the legible scribing "11 WS" The root-hole of this stump bears S.9°W., 43.6 ft (as per rec.)

New - The previously described brass cap monument is reset at the position indicated by the described accessories fd. The stamping "RESET DCSO 2011" is added the brass cap. The BC monument is firmly and plumbly set.

A 6" DBH D.Fir (slight pistol-butt) scribed "T21S R11W S21 CS" "BT" on a double blaze; bears N.66°E., 3.9 ft.

A 12" DBH D.Fir (slight pistol-butt) scribed "T21S R11W S29 CS" "BT" on a double blaze; bears S.6°E., 27.8 ft.

A 7" DBH D.Fir (Major pistol-butt on an "S" curve in the trunk at 3+ ft high) scribed "T21S R11W CS" "BT" on a double blaze; bears S.44°W., 25.2 ft.

Note - Monument is on very steep WSW slope in mixed fir, alder & spruce forest. Monument is approx. 250 ft. easterly from and 200 ft. higher than a dirt forest access road.

Decl. 16°E.