

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 16 and 17

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by John W. Meldrum, Deputy surveyor, under Contract #116, dated December 16, 1866 (DCSO records Vol. 3 Page(s) 1159)

Set ¼ sec. post, from which
A Maple 8" dia., bears N.52°W., 38 lks. dist.
An Alder 12" dia., bears N.82°E., 6 lks. dist.

F.C. Frear, Deputy Co. Surveyor - W.F. Peck and Cowan, Witnesses - May 17, 1918 - Vol 3 Pg 28; F.B. 45 Pgs. 6-9 and ("old" renewal book Page 16)

A reestablishment. No old trees or cor. found.
Set in 5" x 48" Cedar stake, from which
A 14' Fir bears N.48½°W., 7.6 ft.
A 12" Fir bears S.31½°E., 4.9 ft.

Douglas Co. Surveyors Office - James W. Byron - Sept. 22, 1959 - C.S. File 49/186

Found both BTs as recorded by Frear, barked scribed ¼ S BT.
Set Brass cap at cor. mkd: "County Surveyors Office 1959".
I rescribe Frear's BTs:
21" R.Fir N.48½°W., 7.8 ft. scribed "¼ S17 CS BT"
17" R.Fir S.31½°E., 5.6 ft. scribed "¼ S16 CS BT"

Survey by Richard J. Hintz - Nov. 1974 - C.S. File 58/17

Found - 1959 County brass cap and I.P.
21" Fir bears N.48½°W., 7.8 ft, now a stump cut below scribe.
17" Fir bears S.31½°E., 5.6 ft. now a stump cut below scribe.
New BT - 24" Fir bears N.77½°E., 15.1 ft. scribed ¼ S16 BT

Survey by Ronald G. Geisler - For: Champion International Corp. - Nov. 1982 - C.S. File 58/278 and M 93-34

Found - 1959 DCSO brass cap with iron pipe.
22" Fir stump bears N.44°W., (Rec. N.48½°W.) 7.7 ft. No scribing visible.
16" Fir stump bears S.31°E., 5.7 ft. No scribing visible.
27" Fir bears N.77°E., 15.3 ft. Healed blaze. No scribing visible.
New BT - 24" Spruce bears S.18°E., 34.3 ft. scribed W ¼ S16 BT.