

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John W. Meldrum, Deputy surveyor, under Contract #116, dated December 16, 1866 (DCSO records Vol. 3 Page(s) 1162)

Set ¼ sec. post, from which
A Maple 18" dia., bears N.50°W., 23 lks. dist.
An Alder 12" dia., bears S.6°W., 27 lks. dist.

Douglas County Surveyors office - James W. Bryon - V. Tracy; J. Heritage, E. West, crew - June 1967 - C.S. File 54/47 and M 33-18

No trace of original corner or BTs found.
From Hub #77, we go N.78°52'40"E., 35.25 ft., the proportional point for ¼ corner as shown in sketch in CS file
Set Brass cap at cor. mkd: County Surveyors Office
T 21 S_{1/4} $\frac{S}{S}$ $\frac{4}{9}$ R11W
1967

New BTs -9" Spruce N.56°W., 11.3 ft. mkd. ¼ S4 CS BT.
7" Alder S.45°W., 23.4 ft. mkd. ¼ S9 CS BT.
This corner lies 10 ft. W. of 2 ft. wide creek, course SE. and 20 ft. NW of fork in creek course West.

Survey by Robert B. Ward, Jr. - For: U.S. Plywood - Feb. 6, 1976 - C.S. File 59/2-1

Found - 1967 DCSO brass cap properly mkd. and in good shape.
14" D.Fir bears N.55°15'W., 11.6 ft.
New BTs -14" D.Fir bears N.9°45'E., 23.2 ft. scribed T21S R11W S¼ S4.
14" D.Fir bears S.9°30'E., 49.7 ft. scribed T21S R11W N¼ S9.

Fd. OK June 15, 1977 by G Langlitz, DCSO - C.S. File 59/34-40

Tony Hostetter - For: Rome Creek Timber+ - Feb. 2019 - C.S. File 65/103-5

Found - 1988 DCSO brass cap as described by Ward.
22" Fir, face evident, BT tag, bears; N.55°15'W., 11.6 ft. to center.
22" Fir stump, face evident, BT tag, bears; N.9°45'E., 23.2 ft. to center.
New BTs- 16" Cedar, mkd "X", BT tag, bears: N.66°W., 6.4 ft. to spike.