

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 340700

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 4; & 33 of T20-11

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 1 Page(s) 115)

-----  
Set a post 3 ft. long, 3" sq., 18" in the ground for 1/4 sec. cor., marked 1/4 S on N. face; from which

A Fir 27" dia., bears S.51°W., 10 lks. dist. mkd. 1/4 S BT.

A Vine Maple 4" dia., bears N.83°E., 25 lks. dist. mkd. 1/4 S BT.

Survey by Ronald Stuntzner - For: Moore Mill & Lumber - Jan. 23, 1969 - C.S. File 55/103

-----  
Set by proportionate measurement. The 1/4 corner had been searched for but not found.

Set 1" Iron pipe, from which

Bark scribed 32" Fir, N.50°W., 1.8 ft.

Scribed 42" Fir, N.82°E., 9.5 ft.

This corner is approx. 390 ft. East of the Noel Creek Road on a spur ridge.

Douglas Co. Surveyors Office - Larry E. Monrean, Deputy - Karen Cheney; Steve J. Flause, crew - June 15, 1977 - C.S. File 59/34-39

-----  
Found - A 1" Iron pipe at 1/4 cor. by Stuntzner.

32" D.Fir bears N.50°W., 1.8 ft., tree bark scribed "S33 1/4"

42" D.Fir now 52" bears N.82°E., 9.5 ft. Tree has unhealed blaze scribed "S33 1/4".

Set a 1" x 30" I.Pipe with brass cap attached at 1/4 corner as determined by Stuntzner, cap stamped: Douglas Co. Surveyor

T 20 S

1/4      S 33  
          S 4      R11W  
          1977

Set 1" I.P. along easterly edge of cap.

New BT - 48" D.Fir bears S.4 1/2°W., 88.4 ft. Tree double blazed and scribed "1/4 S4 CS BT"

Corner lies at NE corner of stand of timber.

Fd. OK May 20, 1980 by E. Alvarado - C.S. File 61/6-46