

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 and 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by John W. Meldrum, Deputy surveyor, under Contract #116, dated December 16, 1866 (DCSO records Vol. 3 Page(s) 1160-61)

-----  
Set post for cor. to secs. 9, 10, 15 and 16, from which  
A Cedar 36" dia., bears N.60°W., 75 lks. dist.  
An Alder 6" dia., bears N.58°E., 37 lks. dist.  
A Cherry 5" dia., bears S.30°E., 32 lks. dist.  
A Cherry 4" dia., bears S.75°W., 60 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page(s) 1212)

-----  
Cor. of secs. 9, 10, 15 and 16, which is a post, 4" sq., badly decayed, marked T21S S10 on NE.; R11W S15 on SE.; S16 on SW.; S9 on NW. faces with 3 notches on E. and 4 notches on S. edges, from which  
A Cedar 36" dia., bears N.60°W., 75 lks. dist. mkd. T21S R11W S9 BT.  
All other bearing trees are gone.

H.L. Eppstein, County Surveyor - Wit: Bert Lane; Grover Anchors and Harry Burnhardt - June 27, 1926 - C.S. File 4/68 (and "old" corner book, pg. 16)

-----  
Renew corner from old Cedar BT. Other gone.  
Set a 4" x 4" x 36" Fir stake and marked new BTs:  
48" Fir N.23°E., 77 lks.  
15" Cherry S.71°E., 46 lks.  
60" Cedar N.67°W., 107 lks.  
No other tree available in SW. or sec. 16.

Douglas Co. Surveyors Office - R.B. Kimberling; P.L. Earle - March 8, 1978 - C.S. File 59/46-28

-----  
Found - A 3/4" I.P. (no record) 6" above ground next to two square wooden posts.  
An OBT, 36" now 78" Cedar bears N.60°W., 49.5 ft. with a chopped open blaze and rotted out center.  
A 48" now 57" Fir stump bears N.23°E., 51.8 ft. (Rec. 50.8 ft. good to orig. face), with a double well healed blaze.  
A 60" Cedar stump bears N.67°W., 70.6 ft. badly rotted.  
Set a 1" x 36" I.P. over 3/4" I.P. (driven 2.0 ft. below ground) with a brass cap set 6" above ground and marked  
(Cont. Next Page)

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 400500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 9, 10, 15 and 16

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Douglas County Surveyors Office

T 21 S R 11 W

S 9 | S 10

S 16 | S 15

1978

I set squared wooden posts up and down hill on a steep NW. slope.

New BTs -18" Maple bears S.77°E., 78.2 ft. double blaze mkd. T21S R11W S15 CS BT.

12" leaning Maple bears S.15°W., 51.0 ft. double blaze and mkd. T21S R11W S16 CS BT.

19" leaning I.Cedar bears N.21½°W., 41.0 ft. @-31°=35.1 ft. (meas. to center at ground), double blaze and mkd. T21S R11W S9 CS BT.

20" I.Cedar bears N.19½°E., 40.4 ft. @-11°=39.7 ft., double blaze and mkd. T21S R11W S10 CS BT.

Corner is 0.6 mile East of Abbott House up private road then 300 ft. South up canyon and 100 ft. up a NW. slope.