

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by John W. Meldrum, Deputy surveyor, under Contract #116, dated December 16, 1866 (DCSO records Vol. 3 Page(s) 1162)

Set ¼ sec. post, from which
 An Alder 10" dia., bears N.60°W., 27 lks. dist.
 A Maple 12" dia., bears N.20°E., 58 lks. dist.

Douglas County Surveyors Office - Gary L. Langlitz, Deputy - R.B. Kimberling; P.L. Earle; S.J. Flauser, crew - For: Doug. Co. Land Dept. - Sept. 1977 - C.S. File 59/32; C.S. File 59/40-16 and RM 3-13

No monuments or accessories found.
Set a 1" x 30" Iron pipe at ¼ corner position determined by single proportion. Monument set 27" deep, cap is marked:
County Surveyors Office

 T 21 S
 1/4 S 4 | S 3
 R 11 W
 1977

New BTs -A Maple, multi-trunk, 48" bears S.11°E., 55.6 ft. double blaze and scribe "¼ S3 CS BT" on a 10" trunk.
 A 10" Alder bears N.73°W., 33.6 ft. to base. Tree bark scribed "¼ S4 CS BT"
Corner lies on a southerly slope approx. 80 ft. West of N-S cutting line in an old clear cut.