

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 22 and 27

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page(s) 1220)

-----  
Set a sandstone 18x14x8 ins., 12" in the ground, for 1/4 sec. cor. marked 1/4 on N. face, from which  
A Maple 30" dia., bears S.43°W., 30 lks. dist. mkd. 1/4 S BT  
A Fir 42" dia., bears N.64 1/2°E., 305 lks. dist. mkd. 1/4 S BT  
and raised a mound of stone, 1 1/2 ft. high, 2 ft. base alongside.  
Haskell's house bears South, 100 lks.

BLM resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #430, Surveyed June/Aug 1960 (DCSO records Vol. 31 Page(s) 12899-900)

-----  
The 1/4 sec. cor., determined at record bearing and distance from each of the original bearing trees:  
A decayed Fir stump 32" dia., bears N.64 1/2°E., 305 lks. dist., with no marks remaining.  
A Maple 43" dia., bears S.43°W., 30 lks. dist. with a healed and rotted blaze.  
The cor. point has been perpetuated with an iron pipe, 1" dia., projecting 10" above ground.  
At the corner point  
Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, and in a mound of stone 2 1/2 ft. base, to top, with brass cap  
mkd:                    1/4 S 22  
                              S 27  
                              T 21 S R 11 W  
                                  1960  
from which new bearing trees:  
A Fir 11" dia., bears N.72 3/4°W., 60 lks. dist. mkd. 1/4 S22 BT.  
A Fir 23" dia., bears S.80 1/2°W., 85 lks. dist. mkd. 1/4 S27 BT.  
Reset the iron pipe alongside the iron post.

Fd. OK, Feb. 1984 by J. Prochnau - M 96-61 A&B