

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 24

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page(s) 1200)

Set a sandstone 8x8x8 ins. 5" in the ground for ¼ sec. cor. marked ¼ on W. face, and raised a mound of stone 1½ ft. high and 2 ft. base alongside; pits impracticable.

BLM resurvey by Thomas A. Tillman, Civil Engineer (Cadastral), under Group #373, under Special Instructions dated Aug. 6, 1957 - (DCSO records Vol. 29 Page(s) 12334-35)

The ¼ sec. cor. monumented with a sandstone 8x8x8 ins., firmly set 6" in the ground, plainly marked ¼ on W. face, showing no evidence of having been disturbed, and substantiated by an old blaze on a snag about 3 chs. southerly, topography to the North and South and a small mound of stone at the W. side.

At the corner point

Set an iron post 30" long, 2½" dia., 24" in the ground, and in a small mound of stone, to top, with brass cap mkd:

T21S R11W

¼

S 23 S 24

1957

from which

A Fir 26" dia., bears N.27¼°E., 40 lks. dist. mkd. ¼ S24 BT.

A Fir 16" dia., bears N.51½°W., 15½ lks. dist. mkd. ¼ S23 BT.

A Fir 8" dia., bears S.79°20'W., 534 lks. dist. blazed on N., S., E., and W. sides, marked as approx. ¼ sec.cor. with lumber crayon.

Reset the sandstone alongside and E. of the iron post.

The ¼ sec. cor. is located 7 lks. S. of a small gully, drains S.60°W.

Survey by Ronald E. Stuntzner, LS 1342 - For: International Paper Co. and Siuslaw National Forest - May 1980 - M 84-51

Found - 2½" brass cap set in 1957 by BLM.

30" D.Fir bears N.27°E., 26.5 ft.

Other BTs of record not verified.

New BT - 28" D.Fir bears N.14°W., 31.9 ft.