

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 600540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page(s) 1196)

A Cedar 15" dia., which I marked ¼ S on W. side, for ¼ sec. cor., from which

A Fir 36" dia., bears S.45½°E., 10 lks. dist. mkd. ¼ S BT

A Maple 8" dia., bears S.47½°W., 16 lks. dist. mkd. ¼ S BT

Survey by Ronald Stuntzner - For: International Paper Co. - Feb. 3, 1984 - M 96-23

No original BTs found.

Set 3/4" x 30" Iron rod with 2" alum. cap stamped with PLS 1342 and as prescribed, half-way and on line between the SW and NW sec. corners of Sec. 12.

New BTs -30" Cedar bears S.69°W., 18.5 ft., I scribed.

10" Cedar bears S.61°E., 14.9 ft., I scribed.

Corner is on the SE. slope of a hill, 150 ft. above a creek.

Survey by Les Roberts, LS #1039 - For: International Paper Co. - Nov. 20, 1990 - C.S. File 63/126-2 & 15 and M 111-10

Found - 36" Fir stump S.45½°E., 6.6 ft. (1891 BT)

3/4" Iron pin with 1½" alum. cap as set in survey M96-23. Iron pin was set by single proportionate measure and 1891 orig. BT was not found in survey M96-23.

Set 3/4" alum. rod with 3¼" alum. cap Rod was set N.45½°W., 6.6 ft. center measure from found 36" Fir stump.

Buried purple magnetic marker under 36" alum. Rod.

Set 60" alum. post with land monument sign beside post.

3/4" Iron pin set in survey M96-23, bears S.41°50'45"W., 29.24 ft.

New BTs -13" Cedar N.89°W., 9.4 ft. scribed/painted red.

14" Fir N.62°E., 19.6 ft. scribed/painted red.

Corner lies on a South slope about 150 ft. North of creek. Creek bears E and W.