

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 24

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page(s) 1200)

-----  
Set a sandstone 11x10x5 ins. 8" in the ground for ¼ sec.cor. mkd. ¼ S on N. face, and raised a mound of stone 1½ ft. high, 2 ft. base alongside; pits impracticable.

BLM resurvey by Thomas A. Tillman, Civil Engineer (Cadastral), under Group #373, under Special Instructions dated Aug. 6, 1957 - (DCSO records Vol. 29 Page(s) 12333)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 30" long, 2 1/2" dia., 2" in the ground, to bedrock in a mound of stone, 4 ft. base, to top, with brass cap mkd:

T21S R11W  
    S 13  
¼ S 24  
    1957

from which

    A Fir 20" dia., bears N.15°W., 77 lks. dist. mkd. ¼ S13 BT

    A Cedar 48" dia., bears S.42°E., 19 lks. dist. mkd. ¼ S14 BT.

The ¼ sec. cor. is located at bottom of the face of a ledge of sandstone, 6 ft. high, bears E. and W.

Survey by Richard J. Hintz - For: Siuslaw National Forest - July 1986 - M 102-19

-----  
Found - 2½" Iron pipe/brass cap in mound of stone (BLM 1957)  
50" Cedar bears S.40½°E., 11.7 ft. (Rec. S.42°E., 12.5 ft.) with closed face.

24" D.Fir bears N.15 3/4°W., 52.5 ft. (Rec. 50.8 ft.) with closed face.

Set 2½" x 30" alum. pipe with 3¼" USDA-FS alum. cap mkd. "RM ¼ S13 S1°18'E, 42.0 ft. 1986 PLS 497".