

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 640600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 12

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by John W. Meldrum, Deputy surveyor, under Contract #116, dated December 16, 1866 (DCSO records Vol. 3 Page(s) 1169)

Set post for ¼ sec. cor., from which
A Fir 24" dia., bears N.14°E., 44 lks. dist.
A Fir 16" dia., bears S.31°W., 16 lks. dist.

Survey by Robert G. Kintigh - July/Aug. 1956 - C.S. File 42/170

This corner was located midway between the sec. corners common to these two sections.
I Set a 1" x 60" alum. pipe 33" in the ground, from which
24" Cedar with forked top scribed "BT ¼ S1", bears N.64°E., 11.6 ft.
22" Cedar scribed "BT ¼ S12" bears S.77°W., 52.0 ft.

Survey by Ronald E. Stuntzner, PLS #1342 - For: International Paper Co. - Feb. 3, 1984 - M 96-23

Found - 1" alum. pipe, out of position, set by Kintigh, bears N.85°03'W., 118.47 ft.
No original BTs found.
Set 3/4" x 30" iron rod with 2" alum. cap stamped "PLS 1342" and as prescribed, half way between the NW & NE corners of Secs. 12.
New BTs -24" Cedar bears S.7°W., 18.0 ft., I scribed.
12' Alder bears N.52°E., 24.4 ft., I scribed.
Corner is on the South slope of hill.