

PRIMARY CORNER DESCRIPTION NE Cor. Section 1, T22-11

Alias <u>944010</u>	Description <u>NE cor. Tract 37, So. bdy. sec. 36</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by - William H. Byars, Deputy Surveyor, Under Contract No. 279, dated March 5, 1878 - (DCSO records Vol. 4 Page(s) 1739)

Set stone 6x12x18 for cor. to Tps. 21 and 22 S., Rs. 10 and 11 W., from which
An Alder 14" dia., bears N.48°E., 52 lks.
A Fir 48" dia., bears S.45°E., 160 lks.
A Cedar 36" dia., bears S.2°W., 50 lks.
An Alder 14" dia., bears N.22°W., 71 lks.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page(s) 1193)

At the cor. to Tps. 21 and 22 S., R. 10 and 11 W., which is a stone 6x12x18 ins., notches not any more perceptible, from which
A stump of Cedar 36" dia., bears S.2°W., 50 lks. dist., marks visible BT.
An Alder 14" dia., bears N.22°W., 71 lks. dist. mkd. T21S R11W S36 BT.
The other two BTs have been destroyed by fire; I mark:
A Maple 6" dia., bears N.30°E., 7 lks. dist. mkd. T22S R10 & 11 W CC BT.

GLO survey by Aurelius Todd, Deputy Surveyor, under Contract #629, dated April 24, 1894 - (DCSO records Vol. 4 Page(s) 1766)

A stone firmly set 6x12x18 ins. above ground marked with 6 notches on N., E., S. and W. edges for cor. to T21 and 22 S. Rs. 10 and 11 W., from which
A Cedar stump 36" dia., bears S.2°W., 50 ks. dist. mkd. T22S R11W S1 BT.
An Alder 14" dia., bears N.22°W., 71 lks. dist. mkd. T21S R11W CC BT.
A Maple 6" dia., bears N.30°E., 7 lks. dist. mkd. T21S R10W CC BT.

Extracts from Homestead Entry Survey No. 130, made by Frank D. Maxwell, Surveyor Forest Service, under Special Instructions dated March 12, 1914 (DCSO records Vol. 5 Page(s) 1850-51) (and duplicate page 11994)

After diligent search I am unable to find any trace of the stone reported set for this cor.
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION NE Cor. Section 1, T22-11

Alias <u>934010</u>	Description <u>NE tract 37 on S. bdy. sec. 36</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

The point for this cor. falls on a very steep NE. slope, covered with fern, brake and undergrowth. The soil is very deep and loose, and of a sliding nature. I presume the stone set for this cor. had either slid into the ravine or is covered up beneath the surface of the ground. I make a careful search for the stone, clearing off the undergrowth and digging into the earth. I find a Maple tree, 9" dia., (dead and in a leaning position), which has a long axe blaze, the center of which is about 3 ft. from the ground. I am unable to make out any scribe marks, the inside of the blaze being decayed. I set a temp. stake S.30°00'W., 7 lks. dist. from the tree (if standing erect), from which

A Cedar stump (lying on the ground in a bad state of decay) would bear S.2°00'W., 50 lks. if standing erect.

An Alder 20" dia., bears N.24°00'W., 118 lks. dist. This tree has a long axe blaze facing the temp. stake. The inside of the blaze is so decayed I am unable to make out any scribe marks.

I make diligent search N., S., E. and W. of this point for a distance of a number of chains in search for further evidences, but find none. As the general description and topography along the line so closely agrees with the original field notes, and as this point is what has been recognized by the settlers for years as the township cor., I RE-ESTABLISH it as follows:

Set a sandstone 26x10x8 ins., 20" in the ground, for cor. of T22S Rs. 10 and 11 W., marked with 6 notches on E., W. and S. edges, from which,

A Cedar 22" dia., bears S.88°15'E., 58 lks. dist. mkd. T22S R10W S6 BT.

A Fir 6" dia., bears S.26°25'W., 29 lks. dist. mkd. T22S R11W S1 BT.

Original BTs left as found.

Corner report by Frederick W. Rase, Surveyor, Forest Service (at the request of the Surveyor General of Oregon to investigate the township cor. reestablished by Maxwell) - Survey commenced Sept. 1915 - (DCSO records, Vol. 28 Pages 11996 and 11997)

(Pg. 11996)

The cor. of T22S, Rs. 10 and 11 W., which is a sandstone, 8x10x6" above ground, firmly set, marked and witnessed as described by Frank D. Maxwell, in his notes of the reestablishment of this corner.

(Pg. 11997)

(Cont. Next Page)

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 672100

PRIMARY CORNER DESCRIPTION NE Cor. Sec. 1 of T22-11

Alias <u>944010</u>	Description <u>NE cor. Tract 37, So. Bdy. Sec. 36</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

I make a careful and extended search N., S., E. and W. of the reestablished cor. for further traces of the original survey, but find no blazes whatever on any trees within a radius of five chains. The topography along the line and length from the township corner to river bank so nearly coinciding with that as reported in the original notes, together with the fact that the position of the reestablished meander corner (South) checks fairly well with the position of the fence line on the range line S. of the river, convinces me that the corner of T22S Rs. 10 and 11W. has been properly reestablished by Surveyor Maxwell.

Fd. Cor., Jan. 1958 by G.R. Lecklider - M 8-29

Survey by James W. Prochnau PLS #1305 - For: U.S. Forest Service - Aug. 1985 - M 99-21 A&B

Found - Original stone 6" x 12" x 22" in upright position.
Buried stone.
Possible remains of original Cedar BT, now a windfall out of position.
Set a U.S. Forest Service 3¼" alum. cap with magnet on a 2½" x 30" alum. flared pipe mkd: PLS #1305. Also set rock mound.
New BTs -7" R.Cedar S.14°W., 24.8 ft. scribed T22S R11W S1 BT
11" R.Alder, S.22°W., 41.2 ft. scr. T22S R10W S6 BT