

PRIMARY CORNER DESCRIPTION E. Sec. cor. for 13 & 24 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page(s) 1189-90)

-
- A Fir 36" dia., which I marked T21S S18 on NE.; R10W S19 on SE.; R11W S24 on SW.; S13 on NW. sides, with 3 notches on N. and S. sides, for cor. to secs. 18, 19, 13 and 24, from which
 - A Fir 30" dia., bears N.73°E., 28 lks. dist. mkd. T21S R10W S18 BT.
 - A Fir 24" dia., bears S.55°E., 96 lks. dist. mkd. T21S R10W S19 BT.
 - A Fir 15" dia., bears N.89½°W., 15 lks. dist. mkd. T21S R11W S13 BT.
 - A Fir 30" dia., bears S.21°W., 45 lks. dist. mkd. T21S R11W S24 BT.

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1056)

Intersect the old cor. of secs. 13, 18, 19 and 24, which is a Fir 40" dia., mkd. and witnessed as described by the Surveyor General. I obliterate the marks on the NE and SE bearing trees and change this corner to refer to secs. 13 and 24 only.

Fd. Corner tree OK, in BLM resurvey by Thomas Tillman, Group #373, under Special Instructions dated Aug. 1957 (DCSO records, Vol. 29 Page 12332)

Survey by Herman Pieske - For: U.S. Forest Service - Nov. 1984 - M 97-77 A & B

-
- Found - 50" D.Fir corner tree found. Healed faces on North and South sides. Bark scribes "R11W S24" visible on South side; "S1" visible on NW side.
- 46" Obl.D.Fir bears S.64°E., 41.0 ft. Axe work on bark (tag reads obliterated N.55°W 63.41 ft.) (Rec. S.55°E., 63.4 ft.)
 - 54" D.Fir bears S.22°W., 25.2 ft. with healed face.
 - 30" D.Fir bears N.89°W., 17.9 ft. healed burly face.
 - 50" Obl. D.Fir brs N.73°E., 18.5' small healed face.
- Set reference monument, a 2½" x 30" alum. pipe 25" in the ground, with 3¼" alum. cap mkd. "USDA Forest Service T21S R11W S19 RM N.89°44'W 6.0 ft. RLS 1651 1984 Unlawful to Disturb", bears S.89°44'E., 6.0 ft. (Cont. Next Page)

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 700400

PRIMARY CORNER DESCRIPTION E. Sec. Cor. for 13 & 24 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by Richard Hintz -For: Siuslaw National Forest - July 1986 - M 102-19

Found - 36" D.Fir corner tree. Healed faces on N. and S. sides, bark scribed "R11W S24" visible on S., "S1" visible on the NW. side.
46" obliterated D.Fir bears S.64°E., 41.0 ft. (Rec. S.55°E., 63.4 ft.) Axe work on bark.
54" D.Fir bears S.22°W., 25.2 ft. (Rec. S.21°W., 29.7 ft.) with healed face.
30" D.Fir bears N.89°W., 17.9 ft. (Rec. N.89°W., 9.9 ft.) with healed face.
50" obliterated D.Fir, bears N.73°E., 18.5 ft. with healed face.
Set 2½" x 30" alum. pipe with a ¾" USDA-FS alum. cap mkd. "T21S R11W S19 RM N.89°44'W -6.0' R.L.S. 1651 1984".