

TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 700540

PRIMARY CORNER DESCRIPTION WC ¼ Cor. for Sec. 12; & S. 7, T21-10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page(s) 1187-88)

An Alder 12" dia., which I marked ¼ S on W. face for ¼ sec. cor., from which

An Alder 12" dia., bears S.30°W., 7 lks. dist. mkd. ¼ S BT

An Alder 3' dia., bears S.10°E., 8 lks. dist. mkd. ¼ S BT.

This corner stands in a slide, composed of logs brought down by high water; logs are piled 12 ft. deep. (July 8, 1891)

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 1058)

(40.91 chs.)

Point for ¼ sec. cor. falls in creek.

(40.99 chs.)

Set an iron post 3 ft. long, 1' dia., 26" in the ground, for witness corner to the ¼ sec. corner, with brass cap marked:

¼
S12 | S7
WC
1919

from which

An Alder 16" dia., bears N.67°E., 86 lks. mkd. WC ¼ S7 BT.

An Alder 16" dia., bears S.67°W., 44 lks. mkd. WC ¼ S12 BT

Survey by Herman Pieske, RLS #1651 - For: U.S. Forest Service Nov. 1984 - M 97-77 A&B

Set 2½" x 30" alum. pipe 22" in the ground with 24" dia. mound of stone with ¾" alum. cap mkd: "USDA Forest Service T21S R10W ¼ R11W S12 S7 1984 RLS 1651 Unlawful to Disturb".

New - 29" D.Fir bears S.81°E., 204.6 ft. scribed "¼ S7 BT"

7" Cedar bears S.34°W., 60.4 ft. scribed "¼ S12 BT"

2½" x 30" alum. pipe 26" in the ground with ¾" alum. cap mkd. "USDA Forest Service T21S R10W S7 RM N.19°40'W 50.85 ft. 1984 RLS 1651 Unlawful to Disturb", bears S.19°40'E., 50.85 ft.

Gary Smithers - Aug 2005 - C.S. File 65/54-29

Found - 1984 ¾" Alum. cap on 2½" alum pipe firmly set. We set a 6 foot galvanized steel post alongside the monument. continued next page

