

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 17

| Alias | Description |
|-------|-------------|
| _____ | _____       |
| _____ | _____       |
| _____ | _____       |
| _____ | _____       |

GLO survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 3 Page(s) 1291-92)

Witness qr. sec. cor. is established on the random line South 262 lks. from true corner.

- A Spruce 30" dia., from which
  - A Spruce 48" dia., bears S.36°W., 25 lks. dist.
  - A Spruce 40" dia., bears N.20°E., 37 lks. dist.

BLM resurvey by Glenn F. Goodson, Scott R. McIntyre and Scott R. McMullin, Cadastral Surveyors - Under Group #1064 - Surveyed June/Sept. 1981 - (DCSO records Vol. 44 Page(s) 17205-06)

The ¼ sec. cor., established by person(s) unknown, at record bearing and distance from the original witness cor. to the ¼ sec. cor., and is accepted as the corner, monumented with an iron pipe, 1½" dia., firmly set, projecting 6" above ground, from which a bearing tree mkd. by person(s) unknown:

- A Hemlock 30" dia., bears S.9°E., 63½ lks. dist. with healed blaze.

At the corner point

Set an aluminum post 28" long, 2½" dia., 22" in the ground, directly over the iron pipe, with alum. cap mkd:

T 21 S R 12 W

1/4  $\frac{S \ 8}{S \ 17}$   
1981

from which new bearing trees

- A Hemlock 40" dia., bears N.72¼°E., 67 lks. dist. mkd. ¼ S8 BT.
- A Hemlock 18" dia., bears S.20°E., 55½ lks. dist. mkd. ¼ S17 BT.

From this point, the original witness cor. to the ¼ sec. cor., bears South, 2.62 chs. dist., monumented with the remains of the original corner tree; a sawed Spruce stump 42" dia., no marks visible, from which the remains of the original bearing trees:

- A sawed Spruce stump 52" dia., bears N.20°E., 37 lks. dist., no marks visible.
- A sawed Spruce stump 60" dia., bears S.36°W., 25 lks. dist., no marks visible.

Fd. OK, Jan/Mar. 1982 by Clayton Martin - M 91-61  
Found OK by R. Ward, June 2001 - 2002-0048